## LKK Auto Consultants hence notify 友尼摩哆公司 the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey NIMOTOR COMPANY Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis ... 一樓門牌九十四號 新加坡郵區四一七八八三 No illegal modification(s) is allowed AUTOBAY @ KAKI BUKIT Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883 ELEPHONE: 6748 2795 FAX: 6747 2373 DAIN 452153 Acknowledged by Repairer Signature: Registration No.: 203165/00D TPEQ Date: Xiao Chan. DATE:11/10/2021 OUR REF: UAPL 1487 REPAIR ESTIMATE TO THE SUZUKI EVERY NO:GBK6177C 1 REAR TAILGATE WINDSCREEN MOULDING MC \$ 90.70 1 REAR TAILGATE PANEL Distorted 299,60 \$ 1.248.60 2 REAR TAILGATE HINGES NO MU \$ 192.40 1 REAR TAILGATE LOCK ASSY Degle \$ 215.30 1 REAR TAILGATE LOCK STRIKER MY \$ 43.50 X 1 REAR TAILGATE PULLER GARNISH \$ 28.30 1 1 REAR TAILGATE WEATHERSTRIP LAT \$ 293.40 -1 REAR TAILGATE SUZUKI LOGO 83.60 \$ 1 REAR TAILGATE (EVERY) EMBLEM 35 \$ 74.50 1 REAR TAILGATE OUTER HANDLE HMY 212.30 X 1 RAER TAILGATE INNER TRIM BOARD DEN \$ 224.60 625 1 REAR BUMPER ASSY Distorted \$ 998.40 2 REAR BUMPER SIDE RETAINER NO 124.60 2 REAR BUMPER BRACKET 3904.10 \$ 117.60 1 REAR BUMPER REINFORCEMENT >++ ~~ \$ 354.90 × 2 REAR BUMPER SIDE REFLECTOR 3318.48 \$ 465.00 -1 REAR FLOOR INNER PANEL \$ 532.20 1 REAR FLOOR OUTER PANEL Dended. \$ 445.70 ~ 2 REAR PANEL AIR DUCT RH DUCT 269.20 134.60 \$ 2 REAR FENDER SIDE GARNISH HOW 126.80 × 1 REAR EXHAUST PIPE Pers 778.60 X 2 REAR EXHAUST RUBBER MOUNTING AND A 58.80 \$ 1 REAR SPARE TYRE HOLDING ASSY BENT 448.60 /95 \$ S 7,427,60 \$ 742.76 6,684,84 SPECIAL NETT:-1 REAR 70KM/H STICKET \$ 15.00 340 1 REAR 5 PAX STICKET 15.00 \$ 1 REAR REVESE SENSOR Dand \$ 280.00 200 1 REAR WINDSCREEN DAM RUBBER XW \$ 60.00 1 REAR NUMBER PLATE \$ 50.00 LABOUR CHARGES:-TO SPRAY UNDERCOATING IN REPAIR 180.00 60 2140 TO DISM/REFIX REAR WINDSCREEN GLASS 180.00 120 TO DISM/RENEW REAR REVESE SENSOR 80.00 50 TO DISM/RENEW REAR EXHAUST PIPE AFTER REPAIR 100.00 80 TO DISM/REWIRE DAMAGED PORTION 250.00 30 TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS 1400 00 1000 TO PUTTY AND RESPRAY DAMAGED PORTION 1,000.00 900 10.294.84