

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-169

DATE : 19-Aug-2021

POLICY NO. : MSIG B29139165APY

VEHICLE REG. NO. : SKL9307M

VEHICLE MAKE : HYUNDAI SANTA FE 2.4L GDI ABS

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 500.00	\$ 500.00
2	Rear Bumper Lower Cover	1	\$ 550.00	\$ 550.00
3	Rear Bumper Lower Skid plate	1	\$ 100.00	\$ 100.00
4	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
5	Rear Bumper Tow Eye Cover	1	\$ 20.00	\$ 20.00
6	Rear Bumper Retainer RH	1	\$ 40.00	\$ 40.00
7	Rear Bumper Retainer LH	1	\$ 40.00	\$ 40.00
8	Rear Bumper Foglamp RH	1	\$ 220.00	\$ 220.00
9	Rear Bumper Foglamp LH	1	\$ 220.00	\$ 220.00
10	Rear Reinforcement	1	\$ 400.00	\$ 400.00
11	Rear Hyundai Emblem	1	\$ 50.00	\$ 50.00
12	Rear SANTA FE Emblem	1	\$ 50.00	\$ 50.00
13	Rear 4WD Emblem	1	\$ 50.00	\$ 50.00
14	Rear Tailgate Door	1	\$ 1,780.00	\$ 1,780.00
15	Rear Tailgate Door Lock	1	\$ 140.00	\$ 140.00
16	Rear Tailgate Door Lock Latch	1	\$ 30.00	\$ 30.00
17	Rear Tailgate Door Rubber Seal	1	\$ 180.00	\$ 180.00
18	Rear Tailgate Inner Trim	1	\$ 240.00	\$ 240.00
19	Rear Tailgate Lamp LH	1	\$ 300.00	\$ 300.00
20	Rear Tailgate Gas Spring LH	1	\$ 120.00	\$ 120.00
21	Rear Tail Lamp LH	1	\$ 400.00	\$ 400.00
22	Rear / End Panel Garnish	1	\$ 120.00	\$ 120.00
23	End Panel	1	\$ 380.00	\$ 380.00
24	Antenna Assy - Smart Key	1	\$ 120.00	\$ 120.00
25	Rear Windscreen Molding	1	\$ 120.00	\$ 120.00
26	Rear Reverse Sensor RH	1	\$ 250.00	\$ 250.00
27	Rear Reverse Sensor LH	1	\$ 250.00	\$ 250.00
28	Rear Reverse Sensor Wiring Harness	1	\$ 220.00	\$ 220.00
29	Rear Exhaust Muffler	1	\$ 1,000.00	\$ 1,000.00
30	Rear Exhaust Muffler Rubber Bush	2	\$ 40.00	\$ 80.00
Total Spare Parts				\$ 6,500.00
	<u>SPECIAL NETT</u>			

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-169

DATE : 19-Aug-2021

POLICY NO. : MSIG B29139165APY

VEHICLE REG. NO. : SKL9307M

VEHICLE MAKE : HYUNDAI SANTA FE 2.4L GDI ABS

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
31	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
32	Rear License Plate	1	\$ 40.00	\$ 40.00
Total Special Nett				\$ 80.00
	LABOUR			
33	Spray painting Whole Rear & Blending	1	\$ 1,000.00	\$ 1,000.00
34	Repair and Replace Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00
35	Remove and Replace Rear Windscreen	1	\$ 150.00	\$ 150.00
36	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 120.00	\$ 120.00
37	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 80.00
38	Anti-Rust Tuff Coat	1	\$ 100.00	\$ 100.00
39	Remove and Replace Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
40	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,560.00
Amount Before Excess	\$ 9,140.00
Add GST @ 7%	639.80
Total Amount Payable	\$ 9,779.80