



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-169
DATE : 19-Aug-2021
POLICY NO. : MSIG B29139165APY
VEHICLE REG. NO. : SKL9307M
VEHICLE MAKE : HYUNDAI SANTA FE 2.4L GDI ABS

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>de /</i>	1	\$ 500.00	\$ 500.00
2	Rear Bumper Lower Cover <i>de /</i>	1	\$ 550.00	\$ 550.00
3	Rear Bumper Lower Skid plate <i>de /</i>	1	\$ 100.00	\$ 100.00
4	Rear Bumper Clips <i>per / s/n</i>	10	\$ 5.00	\$ 50.00 <i>30 s/n</i>
5	Rear Bumper Tow Eye Cover <i>X</i>	1	\$ 20.00	\$ 20.00
6	Rear Bumper Retainer RH <i>X</i>	1	\$ 40.00	\$ 40.00
7	Rear Bumper Retainer LH <i>X</i>	1	\$ 40.00	\$ 40.00
8	Rear Bumper Foglamp RH <i>X</i>	1	\$ 220.00	\$ 220.00
9	Rear Bumper Foglamp LH <i>RCM /</i>	1	\$ 220.00	\$ 220.00
10	Rear Reinforcement <i>bt /</i>	1	\$ 400.00	\$ 400.00
11	Rear Hyundai Emblem <i>X</i>	1	\$ 50.00	\$ 50.00
12	Rear SANTA FE Emblem <i>per /</i>	1	\$ 50.00	\$ 50.00
13	Rear 4WD Emblem <i>per /</i>	1	\$ 50.00	\$ 50.00
14	Rear Tailgate Door <i>bm /</i>	1	\$ 1,780.00	\$ 1,780.00
15	Rear Tailgate Door Lock <i>cut /</i>	1	\$ 140.00	\$ 140.00
16	Rear Tailgate Door Lock Latch <i>X</i>	1	\$ 30.00	\$ 30.00
17	Rear Tailgate Door Rubber Seal <i>per /</i>	1	\$ 180.00	\$ 180.00
18	Rear Tailgate Inner Trim <i>X</i>	1	\$ 240.00	\$ 240.00
19	Rear Tailgate Lamp LH <i>X</i>	1	\$ 300.00	\$ 300.00
20	Rear Tailgate Gas Spring LH <i>X</i>	1	\$ 120.00	\$ 120.00
21	Rear Tail Lamp LH <i>X</i>	1	\$ 400.00	\$ 400.00
22	Rear / End Panel Garnish <i>X</i>	1	\$ 120.00	\$ 120.00
23	End Panel <i>repair</i>	1	\$ 380.00	\$ 380.00
24	Antenna Assy - Smart Key <i>X</i>	1	\$ 120.00	\$ 120.00
25	Rear Windscreen Molding <i>per X</i>	1	\$ 120.00	\$ 120.00
26	Rear Reverse Sensor RH <i>3 An - s/n</i>	1	\$ 250.00	\$ 250.00 <i>200 -</i>
27	Rear Reverse Sensor LH <i>X</i>	1	\$ 250.00	\$ 250.00
28	Rear Reverse Sensor Wiring Harness <i>X</i>	1	\$ 220.00	\$ 220.00
29	Rear Exhaust Muffler <i>X</i>	1	\$ 1,000.00	\$ 1,000.00
30	Rear Exhaust Muffler Rubber Bush <i>X</i>	2	\$ 40.00	\$ 80.00
Total Spare Parts				\$ 6,500.00
SPECIAL NETT				



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-169
DATE : 19-Aug-2021
POLICY NO. : MSIG B29139165APY
VEHICLE REG. NO. : SKL9307M
VEHICLE MAKE : HYUNDAI SANTA FE 2.4L GDI ABS

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

*Rasul - Hp 90010068
28/08/12 @ 1050 / 5 days / 4/5
Reng after repair*

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
31	Rear Windscreen Sealant <i>ne</i>	1	\$ 40.00	\$ 40.00
32	Rear License Plate <i>sur</i>	1	\$ 40.00	\$ 40.00
Total Special Nett				\$ 80.00
LABOUR				
33	Spray painting Whole Rear & Blending	1	\$ 1,000.00	\$ 1,000.00
34	Repair and Replace Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00
35	Remove and Replace Rear Windscreen	1	\$ 150.00	\$ 150.00
36	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 120.00	\$ 120.00
37	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 80.00
38	Anti-Rust Tuff Coat	1	\$ 100.00	\$ 100.00
39	Remove and Replace Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
40	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,560.00
Amount Before Excess				\$ 9,140.00
Add GST @ 7%				639.80
Total Amount Payable				\$ 9,779.80

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: