



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 8398D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DISTORTED	1,685.00	1,414.00
2	REAR BUMPER PDC SENSORS @\$255.00	SHORTED	510.00	232.00
4	REAR BUMPER PDC SENSOR HOLDERS @\$25.00	NECESSARY	100.00	100.00
2	REAR BUMPER SIDE GRILLES @\$265.00	O/S CUT / WARPED	530.00	245.00
2	REAR BUMPER SIDE RETAINERS @\$85.00	O/S CRACKED	170.00	32.50
1	SET REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	REAR AIR VENT O/S	CRACKED	182.00	166.20
1	TAILGATE	NOT NECESSARY	1,742.00	-
1	TAILGATE "E-POWER" EMBLEM	NOT NECESSARY	105.00	-
1	TAILGATE REAR LOGO	NOT NECESSARY	48.00	-
1	TAILGATE "HIGHWAY" EMBLEM	NOT NECESSARY	90.00	-
1	TAILGATE "STAR" EMBLEM	NOT NECESSARY	88.00	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	299.00	-
1	TAILGATE INNER LOCK	NOT NECESSARY	509.00	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	615.00	-
1	TAILLAMP O/S	CRACKED	660.30	660.30
1	TAILLAMP LOWER GARNISH O/S	TORN	484.90	384.90
1	TAILLAMP LOWER GARNISH SIDE RETAINER O/S	CRACKED	146.00	146.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	455.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	242.00	-
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	1,917.00	-
1	REAR FENDER INNER TRIM BOARD O/S	NOT NECESSARY	628.20	-
1	REAR FENDER UNDER TRIM O/S	DISTORTED	366.20	282.50
1	SET REAR FENDER UNDER TRIM CLIPS O/S	NECESSARY	30.00	30.00
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	168.00	-
1	REAR WINDSCREEN SEALANT	NOT NECESSARY	45.00	-
	LESS 10% DISCOUNT		-	-373.84
			11,860.60	3,364.56

Report Ref No. CS/SMR21008732/Uuf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX TAILGATE MECHANISM.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		180.00	100.00
	TO RESET & REPROGRAMME SYSTEM.		180.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR FENDER O/S.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			3,540.00	1,650.00
	<b>GRAND TOTAL</b>		<b>15,400.60</b>	<b>5,014.56</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>5,014.56</b>

Report Ref No. CS/SMR21008732/Uuf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.