NS/INC21008739/T1qc

INC ASSIGNMENT SHA 3356D Yr Regn: 2019, April-From: Veh No: Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or To Inspect Vehicle No: Make: at Workshop m/s Colour A/C: Insured / Std / NI / NA Sp.Reading T/Radlo: Insured / Std / NI / NA Insured: Eng/No: Policy No. C/No: MT/1141369-002 Claims No. Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured: Excess: Brake: Inorden/Jammed/Leaked/Burnt or (Client's Record) Modl: NII / SIRIM / STD A/RIM or Make of Veh; Tyre Size: (Policy Condition) N/S OIS BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / Remark: The veh had commenced its west take repair at the time of inspection. TOYO/YOKO or Rear Front Bal. or Market Value: R/Bal. mm Consistent? : Yes or No R/Bal. IDAC Accident Rport: L/Bal. mm Consistent?: Yes or No GIA / PR Seen: D.O.I. Res.: Yes or No D.O.A. days Est. Repairs: 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages : Frt / Real / O/S / N/S / U/C /Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Date / Time | Action / Instruction 13/09/21@6.51pm Taufikh finalised with Ms Loke LS \$1900, 3 days. (Red \$3785.96, 67%) Date/Time, File Pass to? : Prell. Report Days Of Repair: Resurvey No. of Trip: Survey Fee: : Final Report 15/09 Typist Transportation: Date/Time, File Return to? Add Fee: : Site Insp (\$ _S + RS.__SI : Interview (\$ Photos : Tech. Invs (\$ Others Repert Former: Lung Sum / HEAL (* 1900 Weellend (S TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3356D

Make

: HYUNDAI

Model : IONIQ(G2)

45

Date: 18/08/2021 Insurance: NTUC

MVA: MS. LOKE YY

					Control of the last of the las
Parts Description / La	abour	Туре	Unit Pric	е	Amount
1 REAR BUMPER COVER				A	\$459.4
10 REAR BUMPER CLIPS					\$22.0
1 REAR BUMPER CENTRE MOULDING AS	SY				\$451.2
1 REAR BUMPER BRACKET RH					\$55.8
1 REAR BUMPER REINFORCEMENT					\$394.
	CKET RH				\$138.
The second secon					sut \$155.
					× \$41.
					× \$98.
					X \$201.
					7, \$85.
					Ry \$2,480.
					\$24.
					ne \$24.
1 EMBLEM – IONIQ					ΨΟ1.
1 REAR PANEL					\$532.
1 REAR PANEL GARNISH					\$346.
	SUB TOTAL				\$4,663.
	LESS 20%				\$932
	DISCOUNTED TOTAL				\$3,730
				1001	X
The state of the s	/ER			-10%	\$55
					\$33
1 BOOTLID COMFORT LOGO STICKER					
1 BOOTLID COMFORT APP STICKER	LKK Auto Consulta	ts hence no	tify		\$30
1 BOOTLID ADVERTISEMENT LOGO	the Repairer of the	following:			\$100
1 REAR BUMPER ADVERTISEMENT LOG	To resurvey before/af	er spray paintin	g		\$30
1 REAR BUMPER REVERSE SENSOR	To display damaged p Dads prices are subjective.	art(s) during re-	urvey n	-10%	M \$180
	Third party survey is a	n a "Without Pr	ejudice" basis		\$425
	 No illegal modification 	ns) is allowed			
Labour Charge	Supplementary item(: subject to final appl	must be result	veyed and		576
PANEL BEATING	is subject to final app	ovar ironi insai	and company		\$800
SPRAY PAINTING CHARGE	Acknowledged by Repa	arer			\$600
WIRING CHARGE	Signature:				\$50
REMOVE/REFIX REVERSE SENSOR	Date:				20 \$80
Jahm 97495749					7
- MP) (4/4/21 6340	TOTAL LABOUR	₹			\$1,530
1/2 hour aft uppe					
		1	1		\$5.60E
In a list outs in	ESTIMATE TOTAL	-			\$5,685
	1 REAR BUMPER COVER 10 REAR BUMPER CLIPS 1 REAR BUMPER CENTRE MOULDING AS 1 REAR BUMPER BRACKET RH 1 REAR BUMPER REINFORCEMENT 1 REAR BUMPER REINFORCEMENT BRACKET RH 1 REAR BUMPER REINFORCEMENT BRACKET RH 1 REAR BUMPER LOWER CTR MOULDING 1 REAR BUMPER TOWING COVER 1 REAR BUMPER FOG LAMP 1 LICENCE LAMP 1 BOOTLID 1 BOOTLID HYUNDAI PLATE 1 EMBLEM HYBRID 1 EMBLEM – IONIQ 1 REAR PANEL 1 REAR PANEL GARNISH 1 REAR PANEL GARNISH 1 REAR BUMPER ADVERTISEMENT LOGO 1 REAR BUMPER ADVERTISEMENT LOG 1 REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE WIRING CHARGE	10 REAR BUMPER CLIPS 1 REAR BUMPER CENTRE MOULDING ASSY 1 REAR BUMPER BRACKET RH 1 REAR BUMPER REINFORCEMENT 1 REAR BUMPER REINFORCEMENT BRACKET RH 1 REAR BUMPER LOWER CTR MOULDING 1 REAR BUMPER REFLECTOR LAMP RH 1 REAR BUMPER TOWING COVER 1 REAR BUMPER FOG LAMP 1 LICENCE LAMP 1 BOOTLID 1 BOOTLID HYUNDAI PLATE 1 EMBLEM HYBRID 1 EMBLEM – IONIQ 1 REAR PANEL 1 REAR PANEL GARNISH SUB TOTAL LESS 20% DISCOUNTED TOTAL 1 REAR NUMBER PLATE WITH TRIM COVER 1 BOOTLID COMFORT TEL NO STICKER 1 BOOTLID COMFORT APP STICKER 1 BOOTLID ADVERTISEMENT LOGO 1 REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE WIRING CHARGE WIRING CHARGE REMOVE/REFIX REVERSE SENSOR 1 REAR BUMPER REVERSE SENSOR Acknowledged by Repairs Signature: Date:	1 REAR BUMPER COVER 10 REAR BUMPER CLIPS 1 REAR BUMPER CENTRE MOULDING ASSY 1 REAR BUMPER BRACKET RH 1 REAR BUMPER REINFORCEMENT 1 REAR BUMPER REINFORCEMENT BRACKET RH 1 REAR BUMPER LOWER CTR MOULDING 1 REAR BUMPER TOWING COVER 1 REAR BUMPER FOG LAMP 1 LICENCE LAMP 1 BOOTLID 1 BOOTLID HYUNDAI PLATE 1 EMBLEM HYBRID 1 EMBLEM – IONIQ 1 REAR PANEL 1 REAR PANEL GARNISH SUB TOTAL LESS 20% DISCOUNTED TOTAL 1 REAR NUMBER PLATE WITH TRIM COVER 1 BOOTLID COMFORT TEL NO STICKER 1 BOOTLID COMFORT LOGO STICKER 1 BOOTLID ADVERTISEMENT LOGO 1 REAR BUMPER ADVERTISEMENT LOGO 1 REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE WIRING CHARGE WIRING CHARGE WIRING CHARGE WIRING CHARGE	REAR BUMPER COVER 10 REAR BUMPER CLIPS 1 REAR BUMPER CENTRE MOULDING ASSY 1 REAR BUMPER REINFORCEMENT 1 REAR BUMPER REINFORCEMENT 1 REAR BUMPER REINFORCEMENT BRACKET RH 1 REAR BUMPER REFLECTOR LAMP RH 1 REAR BUMPER TOWING COVER 1 REAR BUMPER FOG LAMP 1 LICENCE LAMP 1 BOOTLID HYUNDAI PLATE 1 EMBLEM HYBRID 1 EMBLEM - IONIQ 1 REAR PANEL 1 REAR NUMBER PLATE WITH TRIM COVER 1 BOOTLID COMFORT TEL NO STICKER 1 BOOTLID COMFORT APP STICKER 1 BOOTLID ADVERTISEMENT LOGO 1 REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE WIRING CHARGE W	1 REAR BUMPER COVER 10 REAR BUMPER CLIPS 1 REAR BUMPER CENTRE MOULDING ASSY 1 REAR BUMPER BRACKET RH 1 REAR BUMPER REINFORCEMENT 1 REAR BUMPER REINFORCEMENT BRACKET RH 1 REAR BUMPER REINFORCEMENT BRACKET RH 1 REAR BUMPER REPINFORCEMENT BRACKET RH 1 REAR BUMPER TOWING COVER 1 REAR BUMPER TOWING COVER 1 REAR BUMPER FOG LAMP 1 BOOTLID 1 BOOTLID HYUNDAI PLATE 1 EMBLEM HYBRID 1 EMBLEM - IONIQ 1 REAR PANEL 1 REAR PANEL GARNISH SUB TOTAL LESS 20% DISCOUNTED TOTAL 1 REAR PANEL GARNISH SUB TOTAL LESS 20% DISCOUNTED TOTAL 1 REAR PODILID COMFORT TEL NO STICKER 1 BOOTLID COMFORT APP STICKER 2 BOOTLID COMFORT APP STICKER 2 BOOTLID COMFORT APP STICKER 3 BOOTLID COMFORT APP STICKER 4 BOOTLID COMFORT APP STICKER 5 BOOTLID COMFORT APP STICKER 6 BOOTLID COMFOR

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.