



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200317

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/01/2022
Reference CC6/CTI21008743/Ara3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMW 799D
Insured Veh. CB 7875A
Claim No. SNM21D204434/LKKDS
Policy No. DMB1SNW00002032104
Accident Date 10/08/2021
Inspection Date 16/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21008743/Ara3q2 Date: 14/01/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 7875A	Veh. Inspected	SMW 799D	
Policy No.	DMB1SNW00002032104	Coverage (\$)	0.00	
Claim No.	SNM21D204434/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	16/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC250	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDC2533462F163892	Colour	SILVER	
Odometer	54339 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	GOODYEAR	6 mm	
L/H Front Tyre	225/55 R18	GOODYEAR	6 mm	
R/H Rear Tyre	225/55 R18	GOODYEAR	6 mm	
L/H Rear Tyre	225/55 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/08/2021	Inspection Date	16/08/2021	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 799D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOTLID	DENTED	2,915.00	2,510.00
2	REAR BOOTLID @\$192.50	NOT NECESSARY	385.00	-
2	REAR BOOTLID SHOCK ABSORBER @\$682.00	NOT NECESSARY	1,364.00	-
1	REAR BOOTLID UPPER LOCK	DAMAGED	544.50	299.00
1	REAR BOOTLID LOWER LOCK	NOT NECESSARY	335.50	-
1	REAR BOOTLID INNER BOARD	NOT NECESSARY	412.50	-
1	REAR BOOTLID CENTRE EMBLEM	NECESSARY	159.50	159.50
1	REAR BOOTLID 'AMG' EMBLEM	NECESSARY	96.80	96.80
1	SET REAR BOOTLID 'GLC' EMBLEM	NECESSARY	96.80	96.80
1	REAR BOOTLID '250' EMBLEM	NECESSARY	96.80	96.80
2	REAR BOOTLID REFLECTOR @\$709.50	O/S CUT	1,419.00	709.50
1	REAR BOOTLID WEATHERSTRIP	NOT NECESSARY	236.50	-
2	REAR LAMP @\$869.00	O/S CUT	1,738.00	869.00
1	REAR END PANEL	DENTED	1,793.00	1,399.00
1	REAR END PANEL TOP GARNISH	CRACKED	367.50	367.50
1	REAR BUMPER	DEFORMED	1,298.00	1,298.00
2	REAR BUMPER SIDE HOLDER @\$139.70	NOT NECESSARY	279.40	-
1	REAR BUMPER LOWER COVER	CUT	739.20	661.00
1	REAR BUMPER LOWER MOULDING	CUT	458.70	458.70
2	REAR BUMPER LOWER REFLECTOR @\$31.00	NOT NECESSARY	62.00	-
1	REAR BUMPER TOWING HOOK COVER	NOT NECESSARY	60.50	-
1	REAR BUMPER REINFORCEMENT	DENTED	764.50	764.50
2	REAR BUMPER INNER CENTRE GARNISH @\$214.50	NOT NECESSARY	429.00	-
1	REAR BUMPER SPONGE	NOT NECESSARY	154.00	-
1	REAR NUMBER PLATE GARNISH	NOT NECESSARY	93.50	-
2	REAR EXHAUST PIPE CHROME @\$435.60	NOT NECESSARY	871.20	-
1	REAR EXHAUST PIPE TOP COVER	NOT NECESSARY	308.00	-
	LESS 10% DISCOUNT		-1,747.84	-978.61
			15,730.56	8,807.49

Report Ref No. CC6/CTI21008743/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
4	REAR BUMPER REVERSE SENSOR @\$308.00 (SN)	DAMAGED (2 PCS ONLY)	1,848.00	616.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	70.00	30.00
			2,018.00	646.00
	<u>LABOUR</u>			
	TO SUPPLY REAR WINDSCREEN SEALANT .		50.00	50.00
	TO SUPPLY REAR END PANEL INNER SEALANT .	NOT NECESSARY	200.00	-
	REMOVE & REINSTALL REAR WINDSCREEN .		200.00	120.00
	REMOVE & INSTALL SENSOR .		200.00	60.00
	REMOVE & REINSTALL EXHAUST PIPE .	NOT NECESSARY	200.00	-
	REMOVE & REINSTALL BOOTLID INNER GARNISH .		200.00	60.00
	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT .		2,000.00	800.00
	RESPRAY PAINTING.		1,600.00	800.00
	TUFF KOTE.		150.00	30.00
			4,800.00	1,920.00
GRAND TOTAL			22,548.56	11,373.49
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00

Report Ref No. CC6/CTI21008743/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMW 799D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMW 799D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMW 799D

RE-INSPECTION

