

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008745/AEA3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100473580
Claimant Vehicle No :	SKG8308T	Insured Vehicle No :	SLD8890G
Date of Loss:	19/08/2021	Nature of Claim:	TP
		Claim No:	2414204101SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG8308T		
Make & Model:	MAZDA 6, 2.0 SEDAN EXECUTIVE 2WD (A)	Engine No:	PE21259839
Reg. Date:	29/07/2019 (Man. Year: 2018)	Chassis No:	JM6GL1072K0312574
Colour:	Bronze	Odometer:	35614 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,522.08	5,259.60	7,262.48	58.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	3,020.00	1,980.00	39.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,522.08	8,279.60	9,242.48	52.75
Approved Total (Overridden) (S\$)		6,600.00		

(S\$)	17,522.08	6,600.00	10,922.08	62.33
+ GST 7.00/7.00% (S\$)	1,226.55	462.00	764.55	62.33
Nett Amount (S\$)	18,748.63	7,062.00	11,686.63	62.33
+ Loss of Use (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,098.45		
Global Sum Settlement (S\$)		8,090.00		

INSPECTION

Date of Assignment: 20/08/2021

Date Inspected: 20/08/2021

Inspected At:

Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (NPA)	Repair	0.00 FL	*- FL
2	14		*FRONT BUMPER CLIPS	Not Necessary	70.00 FS	*- FS
3	1		*FRONT N/S FENDER	Dented	460.40 FL	*460.40 FL
4	1		*FRONT N/S FENDER WHEEL GUARD	Deformed	245.60 FL	*245.60 FL
5	8		*FRONT N/S FENDER WHEEL GUARD CLIPS	Necessary	40.00 FS	*20.00 FS
6	1		*FRONT N/S DOOR	Dented	1,170.20 FL	*1,170.20 FL
7	1		*FRONT N/S DOOR WEATHERSTRIP	Cut	134.60 FL	*134.60 FL
8	1		*FRONT N/S DOOR WINDOW SEAL (OUTER)	Not Necessary	80.00 FL	*- FL
9	2		*FRONT N/S DOOR HINGES (UPPER & LOWER)	Not Necessary	220.00 FL	*- FL
10	1		*FRONT N/S DOOR STRIKER	Not Necessary	146.50 FL	*- FL
11	1		*FRONT N/S DOOR WINDOW REGULATOR	Damaged	369.70 FL	*369.70 FL
12	1		*FRONT N/S DOOR WINDOW MOTOR	Not Necessary	220.60 FL	*- FL
13	1		*FRONT N/S DOOR WINDOW FRAME CHROME(UPPER)	Not Necessary	123.50 FL	*- FL
14	1		*FRONT N/S DOOR WINDOW FRAME CHROME(LOWER)	Not Necessary	133.00 FL	*- FL
15	1		*FRONT N/S DOOR LOCK	Not Necessary	260.40 FL	*- FL
16	1		*FRONT N/S DOOR LOCK(CATCH)	Not Necessary	110.00 FL	*- FL
17	1		*FRONT N/S DOOR WINDOW CHANNEL	Not Necessary	325.40 FL	*- FL
18	1		*FRONT N/S DOOR WINDOW CHANNEL BRACKET	Not Necessary	87.50 FL	*- FL
19	1		*FRONT N/S DOOR WING MIRROR (NPA)	Repair	0.00 FL	*- FL
20	1		*FRONT N/S DOOR PILLAR (OUTER) (NPA)	Repair	0.00 FL	*- FL
21	1		*FRONT N/S WHEEL RIM	Cut	1,148.88 FS	*650.00 FS
22	1		*FRONT N/S TYRE	Not Necessary	200.00 FS	*- FS
23	1		*FRONT N/S SUSPENSION	Not Necessary	470.80 FL	*- FL
24	1		*FRONT N/S LOWER ARM	Bent	604.60 FL	*452.00 FL
25	1		*FRONT N/S STEERING TIE ROD END	Not Necessary	143.10 FL	*- FL
26	1		*FRONT N/S STEERING BALL JOINT	Not Necessary	147.20 FL	*- FL
27	1		*FRONT N/S STEERING LINKAGE	Not Necessary	84.90 FL	*- FL
28	1		*FRONT N/S KNUCKLE	Not Necessary	453.70 FL	*- FL
29	1		*FRONT N/S WHEEL BEARING	Damaged	680.00 FL	*256.00 FL
30	1		*REAR N/S DOOR	Dented	1,574.60 FL	*1,312.00 FL
31	1		*REAR N/S DOOR WEATHERSTRIP	Not Necessary	144.60 FL	*- FL
32	1		*REAR N/S DOOR LOCK	Not Necessary	264.60 FL	*- FL
33	1		*REAR N/S DOOR WINDOW FRAME CHROME (UPPER)	Not Necessary	123.50 FL	*- FL
34	1		*REAR N/S DOOR WINDOW FRAME CHROME (LOWER)	Not Necessary	133.00 FL	*- FL
35	1		*REAR N/S FENDER (NPA)	Repair	0.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR N/S WHEEL RIM	Cut	1,148.88 FS	*650.00 FS
37	1		*REAR N/S TYRE	Not Necessary	200.00 FS	*- FS
38	1		*REAR N/S SUSPENSION	Not Necessary	386.60 FL	*- FL
39	1		*REAR N/S LOWER ARM	Not Necessary	327.20 FL	*- FL
40	1		*REAR N/S UPPER ARM	Not Necessary	213.50 FL	*- FL
41	1		*REAR N/S STABILIZER LINKAGE	Not Necessary	289.30 FL	*- FL
42	1		*REAR N/S KNUCKLE	Not Necessary	453.70 FL	*- FL
43	1		*REAR N/S WHEEL BEARING	Not Necessary	680.00 FL	*- FL
44	1		*REAR ANTI ROLL BAR	Not Necessary	356.60 FL	*- FL
45	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
46	1		*FRONT N/S DOOR INNER BOARD	Cracked	524.00 FL	*524.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,950.66	6,244.50
- List Item Discount on L Items 20.00/20.00% (S\$)	2,428.58	984.90
Total Parts (S\$)	12,522.08	5,259.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ,STRAIGHTEN AND WELDING	New	1,800.00	1,100.00
2	TO SPRAY PAINTING	New	1,600.00	1,400.00
3	TO REMOVE AND REPLACE FRONT AND REAR N/S UNDER CARRIAGE	New	600.00	200.00
4	TO CHECK WHEEL ALIGNMENT (BEFORE & AFTER)	New	150.00	80.00
5	TO PRESS BEARING	New	200.00	0.00
6	TO REMOVE AND REPLACE FRONT AND REAR N/S DOOR FITTINGS	New	280.00	160.00
7	TO CHECK AND RESET FAULT CODE	New	180.00	0.00
8	TO CHECK WIRING	New	140.00	30.00
9	TO RE-SEAL ANTI RUST	New	50.00	50.00
Gross Labour Cost (\$\$)			5,000.00	3,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >