

ESTIMATE OF REPAIR

Veh# : SKG8308T

Accident Date 19/8/2021

Location BEDOK AVE 3

Model:

MAZDA 6

(29/8/2020)

3P: SLD8890 (AIG)

TPA16-

Asher.

JM6641072K0312574

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Repair</i>	Repair	<i>x</i>	
2	14 pcs	Front bumper clips <i>new</i>		70.00	<i>x</i>
3	1 pc	Front n/s fender <i>Dented</i>	460.40	<i>✓</i>	
4	1 pc	Front n/s fender wheel guard <i>Dented</i>	245.60	<i>✓</i>	
5	8pc	Front n/s fender wheel guard clips <i>new</i>		40.00	<i>20</i>
6	1 pc	Front n/s door <i>Dented</i>	1,170.20	<i>✓</i>	
7	1 pc	Front n/s door weatherstrip <i>new</i>	134.60	<i>✓</i>	
8	1 pc	Front n/s door window seal (outer) <i>new</i>	80.00	<i>x</i>	
9	2 pcs	Front n/s door hinges (upper & lower) <i>new</i>	220.00	<i>x</i>	
10	1 pc	Front n/s door striker <i>new</i>	146.50	<i>x</i>	
11	1 pc	Front n/s door window regulator <i>Damaged</i>	369.70	<i>✓</i>	
12	1 pc	Front n/s door window motor <i>new</i>	220.60	<i>x</i>	
13	1 pc	Front n/s door window frame chrome (upper) <i>new</i>	123.50	<i>x</i>	
14	1 pc	Front n/s door window frame chrome (lower) <i>new</i>	133.00	<i>x</i>	
15	1 pc	Front n/s door lock <i>new</i>	260.40	<i>x</i>	
16	1 pc	Front n/s door lock (catch) <i>new</i>	110.00	<i>x</i>	
17	1 pc	Front n/s door window channel <i>new</i>	325.40	<i>x</i>	
18	1 pc	Front n/s door window channel bracket <i>new</i>	87.50	<i>x</i>	
19	1 pc	Front n/s door wing mirror <i>Repair</i>	repair	<i>x</i>	
20	1 pc	Front n/s door pillar (outer) <i>Repair</i>	repair	<i>x</i>	
21	1 pc	Front n/s wheel rim <i>new</i>	1,436.10	<i>650 (new)</i>	
22	1 pc	Front n/s tyre <i>new</i>		200.00	<i>x</i>
23	1 pc	Front n/s suspension <i>new</i>	470.80	<i>x</i>	
24	1 pc	Front n/s lower arm <i>Dented</i>	604.60	<i>452</i>	
25	1 pc	Front n/s steering tie rod end <i>new</i>	143.10	<i>x</i>	
26	1 pc	Front n/s steering ball joint <i>new</i>	147.20	<i>x</i>	
27	1 pc	Front n/s stabilizer linkage <i>new</i>	84.90	<i>x</i>	
28	1 pc	Front n/s knuckle <i>new</i>	153.70	<i>x</i>	
29	1 pc	Front n/s wheel bearing <i>Dented</i>	680.00	<i>256</i>	
30	1 pc	Rear n/s door <i>Dented</i>	1,574.60	<i>132</i>	
31	1 pc	Rear n/s door weatherstrip <i>new</i>	144.60	<i>x</i>	
32	1 pc	Rear n/s door lock <i>new</i>	264.60	<i>x</i>	

33	1 pc	Rear n/s door window frame chrome (upper) <i>3 M m</i>	123.50	x	
34	1 pc	Rear n/s door window frame chrome (lower) <i>1</i>	133.00	x	
35	1 pc	Rear n/s fender <i>Repair</i>	repair	x	
36	1 pc	Rear n/s wheel rim <i>Area cut</i>	1426.10	650 (SAB)	
37	1 pc	Rear n/s tyre <i>new</i>		200.00	x
38	1 pc	Rear n/s suspension <i>2</i>	386.60	x	
39	1 pc	Rear n/s lower arm	327.20	x	
40	1 pc	Rear n/s upper arm	213.50	x	
41	1 pc	Rear n/s stabilizer linkage <i>2</i>	289.30	x	
42	1 pc	Rear n/s knuckle <i>1</i>	453.70	x	
43	1 pc	Rear n/s wheel bearing	680.00	x	
44	1 pc	Rear anti roll bar	356.60	x	
45	1 pc	Rear bumper <i>Repair</i>	repair	x	
		Front n/s door inner board <i>changed.</i>	Sub-Total:	14,491.10	510.00 0.00
		<i>✓ -524.</i>		20%	0% 0%
			After Less %:	11592.88	510.00 0.00
		Labour			
1		To dismantle, straighten and welding	1,800.00	1100	
2		To spray painting	1,600.00	1400	
3		To remove and replace front and rear n/s under carriage	600.00	200	
4		To check wheel alignment (before & after)	150.00	80	
5		To press bearing	200.00	x	
6		To remove and replace front and rear n/s door <i>hittings</i>	280.00	160	
7		To check and reset fault code	180.00	x	
8		To check wiring	140.00	30	
9		To re-seal anti-rust	50.00	✓	
			Sub-Total:	5,000.00	
			Total:	17,102.88	
			After Less 20%:	13,682.30	



4924.50
3939.60
S.N. 1320

3020

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Admin *L*
H/s 70/08/21
07 Aug



total: 8229.60

H/s: 6.6k.

66k

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer