

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21008746/T1VF3E2

Date: 08/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100366154
Claimant Vehicle No : SLQ7220D Insured Vehicle No : SKM4446Y
Date of Loss: 18/08/2021 Nature of Claim: TP Claim No: 5959085062SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ7220D**
Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGHU691649
Reg. Date: 20/07/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU509382
Colour: Blue Odometer: 85632 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/08/2021
Date Inspected: 20/08/2021 Inspected At: Garage 13 Pte Ltd (HQ)
8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46
Singapore 415875
Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$55,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Missing	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Missing	0.00 F	*- F
3	1		*FRT BUMPER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT BUMPER SPONGE	Deformed	0.00 F	*- F
8	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*- F
9	1		*FRT GRILLE	Cracked	0.00 F	*- F
10	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
11	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*- F
12	1		*FRT SUPPORT PANEL	Cracked	0.00 F	*- F
13	2		*SUPPORT PANEL SIDE GARNISH	Deformed	0.00 F	*- F
14	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
16	1		*BONNET	Bent	0.00 F	*- F
17	1		*BONNET LOCK	Bent	0.00 F	*- F
18	1		*BONNET INSULATOR	Deformed	0.00 F	*- F
19	2		*BONNET HINGE	Bent	0.00 F	*- F
20	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
21	1		*AIR CON FAN ASSY	* Check	0.00 F	*- F
22	1		*RADIATOR	Bent	0.00 F	*- F
23	1		*RADIATOR COWLING	* Check	0.00 F	*- F
24	1		*RADIATOR FAN ASSY	* Check	0.00 F	*- F
25	1		*RADIATOR EXPANSION TANK	Deformed	0.00 F	*- F
26	1		*AIR DUCT	Deformed	0.00 F	*- F
27	1		*AIR CLEANER ASSY	Deformed	0.00 F	*- F
28	1		*FRT EXHAUST MANIFOLD	* Check	0.00 F	*- F
29	1		*FRT LH FENDER	Repair	0.00 F	*- F
30	1		*FRT LH FENDER INNER SHIELD	Deformed	0.00 F	*- F
31	1		*FRT RH FENDER	Bent	0.00 F	*- F
32	1		*FRT RH FENDER INNER SHIELD	Deformed	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >