

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21008747/ATCN2**Date:** 02/11/2021**REFERENCE**

Insured/Claimant:	CHAN MEI LING ALISON	Policy No:	1700094795	
Date of Loss:	13/08/2021	Nature of Claim:	OD	Claim No: 8774020918SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH3033A		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZ601132
Reg. Date:	05/01/2018 (Man. Year: 2017)	Chassis No:	WAUZZZGA6JA043704
Colour:	Orange	Odometer:	60290 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$87,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,592.00	3,873.92	8,718.08	69.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,972.00	1,522.00	6,450.00	80.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,564.00	5,395.92	15,168.08	73.76
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	19,564.00	4,395.92	15,168.08	77.53
+ GST 7.00/7.00% (S\$)	1,369.48	307.71	1,061.77	77.53
Nett Amount (S\$)	20,933.48	4,703.63	16,229.85	77.53

INSPECTION

Date of Assignment:	20/08/2021		
Date Inspected:	19/08/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BUMPER	Distorted	1,042.00 FS	*832.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	347.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE-CENTER	Cracked	197.00 FS	*157.20 FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Cracked	169.00 FS	*135.20 FS
5	1		*FRONT BUMPER AIR GUIDE END CAP-LH	Cracked	59.00 FS	*46.64 FS
6	1		*FRONT BUMPER SPOILER	Cracked	299.00 FS	*238.80 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Torn	156.00 FS	*124.40 FS
8	1		*FRONT WHEEL SPOILER-LH	Not Necessary	34.00 FS	*- FS
9	1		*FRONT BUMPER ADAPTER-LH	Cracked	36.00 FS	*28.32 FS
10	1		*FRONT RADIATOR GRILLE	Cut	1,411.00 FS	*1,128.80 FS
11	1		*FRONT BUMPER STRIKER PLATE	Not Necessary	124.00 FS	*- FS
12	1		*FRONT FOAM FILLER PIECE	Not Necessary	78.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT	Bent	723.00 FS	*578.40 FS
14	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	36.00 FS	*- FS
15	1		*FRONT BUMPER TOP COVER	Not Necessary	100.00 FS	*- FS
16	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
17	1		*AIR CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
18	1		*HORN-LH	Not Necessary	286.00 FS	*- FS
19	1		*HORN BRACKET-LH	Not Necessary	31.00 FS	*- FS
20	1		*FRONT HEADLIGHT MOUNTING	Not Necessary	118.00 FS	*- FS
21	1		*FRONT HEADLIGHT-LH	Not Necessary	4,915.00 FS	*- FS
22	1		*FRONT HEADLIGHT CYLINDER-LH	Not Necessary	142.00 FS	*- FS
23	1		*FRONT HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	182.00 FS	*- FS
24	1		*FRONT LOCK CARRIER	Not Necessary	994.00 FS	*- FS
25	6		*COOLANT	Not Necessary	142.00 FS	*- FS
26	1		*FRONT BUMPER AIR GUIDE-LH	Torn	31.00 FS	*24.16 FS
27	1		*FRONT BUMPER AIR GUIDE-CENTER	Not Necessary	22.00 FS	*- FS
28	2		*FRONT WHEEL ARCH COVER-LH/RH	Necessary	644.00 FS	*514.40 FS
29	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
30	1		*SUNDRIES	Necessary	192.00 FS	*4.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **12,592.00** **3,873.92**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER,ADDITIONAL RADIATOR,RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,700.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,000.00	500.00
5	TO RESPRAY FRONT BUMPER	New	1,200.00	550.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,972.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >