

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21008748/AQCE2**Date:** 12/10/2021**REFERENCE**

Insured/Claimant: PHUA NGEEN BOON Policy No:
Date of Loss: 16/08/2021 Nature of Claim: OD Claim No: 6039964374SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK1877T**
Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZC27186
Reg. Date: 29/03/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V3K1023705
Colour: Blue Odometer: 23874 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$93,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,242.00	11,549.20	6,692.80	36.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,002.00	5,552.00	3,450.00	38.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,244.00	17,101.20	10,142.80	37.23
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	26,944.00	16,801.20	10,142.80	37.64
+ GST 7.00/7.00% (S\$)	1,886.08	1,176.08	710.00	37.64
Nett Amount (S\$)	28,830.08	17,977.28	10,852.80	37.64

INSPECTION

Date of Assignment: 20/08/2021
Date Inspected: 19/08/2021 Inspected At: Premium Automobiles Pte Ltd (Benoi)
24 Benoi Sector
Singapore 629857
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS	
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS	
3	1		*FRONT BUMPER GUIDE SECTION RH	Not Necessary	39.00 FS	*- FS	
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	160.00 FS	*- FS	
5	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	536.00 FS	*- FS	
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	297.00 FS	*- FS	
7	1		*FRONT BUMPER COVER TRIM - RH	Not Necessary	163.00 FS	*- FS	
8	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	38.00 FS	*- FS	
9	1		*FRONT RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS	
10	1		*FRONT RADIATOR GRILLE CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS	
11	1		*FRONT AIR GUIDE GRILLE - RH	Not Necessary	188.00 FS	*- FS	
12	1		*FRONT FOAM FILLER PIECE	Deformed	189.00 FS	*151.20 FS	
13	1		*FRONT REINFORCEMENT BEAM COVER	Torn	122.00 FS	*97.20 FS	
14	1		*FRONT REINFORCEMENT BEAM	Bent	795.00 FS	*636.00 FS	
15	1		*HORN - RH	Not Necessary	200.00 FS	*- FS	
16	1		*FRONT BONNET	Dented	3,134.00 FS	*2,507.20 FS	
17	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS	
18	2		*FRONT BONNET HINGE - LH / RH	Not Necessary	124.00 FS	*- FS	
19	1		*FRONT BONNET CATCH HOOK	Not Necessary	90.00 FS	*- FS	
20	1		*FRONT BONNET STRIKER PLATE - RH	Not Necessary	110.00 FS	*- FS	
21	1		*FRONT BONNET EDGE PROTECTION	Cracked	28.00 FS	*22.00 FS	
22	1		*FRONT BONNET LOCK WITH MICRO SWITCH - RH	Not Necessary	214.00 FS	*- FS	
23	1		*FRONT BONNET BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS	
24	1		*FRONT BONNET LOCK CABLE	Not Necessary	74.00 FS	*- FS	
25	1		*FRONT BONNET CATCH HOOK	Not Necessary	63.00 FS	*- FS	
26	1		*FRONT HEADLIGHT - RH	Cracked	5,455.00 FS	*4,364.00 FS	
27	1		*FRONT HEADLIGHT LIFT CYLINDER - RH	Not Necessary	142.00 FS	*- FS	
28	1		*FRONT HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	68.00 FS	*- FS	
29	1		*FRONT LOCK CARRIER	Cracked	727.00 FS	*581.60 FS	
30	1		*COOLANT (6pc)	Necessary	266.00 FS	*212.64 FS	
31	1		*AIR-CON CONDENSER	Not Necessary	530.00 FS	*- FS	
32	1		*CONDENSER BRACKET	Cracked	19.00 FS	*14.56 FS	
33	1		*FRONT RADIATOR AIR GUIDE - RH	Torn	25.00 FS	*19.44 FS	
34	1		*FRONT AIR GUIDE - RH OUTER	Not Necessary	8.00 FS	*- FS	
35	1		*FRONT RADIATOR AIR GUIDE - UPPER CENTER	Not Necessary	12.00 FS	*- FS	
36	1		*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS	
37	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS	
38	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS	
39	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS	
					Total Parts (\$\$)	18,242.00	11,549.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	2,250.00
5	TO RESPRAY FRONT BUMPER, BONNET AND HINGES	New	2,500.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			9,002.00	5,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >