

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008753/AVCN2**Date:** 26/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00169992000

Claimant Vehicle No : SMR1458H **Insured Vehicle No :** SMW3293B

Date of Loss: 16/08/2021 Nature of Claim: TP Claim No: SNM21D204575/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR1458H**

Make & Model: MAZDA CX-5, 2.0 STANDARD PLUS 2WD I2 (A) Engine No: PE10673871

Reg. Date: 20/12/2019 (Man. Year: 2019) Chassis No: JM6KF2W7AK0330223

Colour: Red Odometer: 21597 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65R17 Rear Tyre Size: 225/65R17

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,995.84	3,538.08	5,457.76	60.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,580.00	1,620.00	50.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,195.84	5,118.08	7,077.76	58.03
Approved Total (Overridden) (\$\$)		4,100.00		
Nett Amount (\$\$)	12,195.84	4,100.00	8,095.84	66.38

INSPECTION

Date of Assignment: 21/08/2021

Date Inspected: 23/08/2021 Inspected At: SD CAR CARE CENTRE
2 KAKI BUKIT AVENUE 2
#01-29 KAKI BUKIT AUTOHUB SINGAPORE 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Oct 2021)

Parts: M1-SUV MAZDA CX-5 2.0 STANDARD PLUS 2WD I2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMR1458H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,587.50 FL	*1,587.50 FL
2	1		*TAILGATE GLASS MOULDING	Necessary	89.60 FL	*89.60 FL
3	1		*TAILGATE OUTER GARNISH	Not Necessary	685.00 FL	*- FL
4	1		*TAILGATE LOGO	Necessary	89.60 FL	*89.60 FL
5	1		*TAILGATE EMBLEM CX-5	Necessary	112.30 FL	*112.30 FL
6	1		*TAILGATE EMBLEM SKYACTIV	Necessary	81.20 FL	*81.20 FL
7	2		*TAILGATE LAMPS-L/R	Not Necessary	998.40 FL	*- FL
8	1		*TAILGATE INNER LOCK	Not Necessary	269.30 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	361.90 FL	*- FL
10	1		*TAILGATE W/STRIP	Not Necessary	160.90 FL	*- FL
11	1		*REAR BUMPER	Deformed	1,278.90 FL	*1,278.90 FL
12	1		*REAR BUMPER TOW COVER	Not Necessary	22.10 FL	*- FL
13	1		*REAR BUMPER TOP HOLDER-CTR	Not Necessary	86.50 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Dented	671.60 FL	*586.00 FL
15	2		*REAR BUMPER BRACKETS	Bent	110.00 FL	*110.00 FL
16	2		*REAR BUMPER SIDE RETAINERS-L/R	Not Necessary	137.20 FL	*- FL
17	1		*REAR END PANEL	Repair	576.10 FL	*- FL
18	1		*REAR END PANEL GARNISH	Not Necessary	178.20 FL	*- FL
19	1		*REAR EXHAUST SILENCER	Not Necessary	1,754.60 FL	*- FL
20	1		*REAR EXHAUST INSULATOR	Not Necessary	180.90 FL	*- FL
21	2		*REAR EXHAUST CHROME PIPES	Not Necessary	231.20 FL	*- FL
22	4		*REAR EXHAUST MOUNTINGS	Not Necessary	180.00 FL	*- FL
23	2		*REAR FENDER WHEEL ARCH GARNISHS-L/R	Not Necessary	520.20 FL	*- FL
24	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	181.60 FL	*- FL
25	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
26	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
27	1		*SET REAR REVERSE SENSOR-4 PCS	Damaged	420.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,104.80	4,325.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,108.96	787.02
Total Parts (\$\$)	8,995.84	3,538.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE,REFIX TAILGATE GLASS	New	180.00	120.00
3	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	150.00	80.00
4	TO RESPRAY UNDERCOATING	New	100.00	40.00
5	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	30.00
6	TO REMOVE,REFIX REVERSE SENSOR/CAMERA	New	80.00	80.00
7	TO REMOVE,REFIX REAR EXHAUST SYSTEMS	New	120.00	0.00
8	TO RESPRAY PAINTING AND ETC	New	1,200.00	600.00
9	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,200.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >