

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21008754/KVF3N2**Date:** 01/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210064626
Claimant Vehicle No :	GBH9159B	Insured Vehicle No :	SNA8289K
Date of Loss:	17/08/2021	Nature of Claim:	TP
		Claim No:	7894829472SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH9159B	Engine No:	YD25429882A
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1MC2E26Z0009402
Reg. Date:	25/10/2018 (Man. Year: 2017)	Odometer:	140941 km
Colour:	Silver		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,027.80	3,944.90	3,082.90	43.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,370.00	290.00	17.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,687.80	5,314.90	3,372.90	38.82
Approved Total (Overridden) (S\$)		4,250.00		
Nett Amount (S\$)	8,687.80	4,250.00	4,437.80	51.08

INSPECTION

Date of Assignment:	20/08/2021	Inspected At:	160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722 REPAIRER: RC AUTO
Date Inspected:	20/08/2021		
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent/Cracked	571.90 F	*571.90 FL
2	2		*FRONT BUMPER FOG LAMP COVER	Missing	235.00 F	*235.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	775.90 F	*528.00 FL
4	1		*FRONT BUMPER LOWER GARNISH	Missing	95.00 F	*95.00 FL
5	1		*FRONT GRILLE	Cracked	527.30 F	*495.00 FL
6	2		*FRONT HEADLAMPS	O/s Mtg Cracked/N/s Broken	783.00 F	*783.00 FL
7	1		*FRONT PANEL	Bent	1,227.50 F	*1,227.50 FL
8	2		*FRONT BUMPER RETAINER	Bent	362.00 F	*362.00 FL
9	1		*FRONT BUMPER BEAM	Repair	235.00 F	*- FL
10	1		*FRONT RADIATOR SMALL	Serviceable	2,121.60 FS	*- FS
11	1		*FRONT NUMBER PLATE	Missing	30.00 FS	*20.00 FS
12	2		*FRONT BUMPER FOG LAMP	Missing	63.60 F	*63.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,027.80	4,381.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	436.10
Total Parts (\$\$)	7,027.80	3,944.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	500.00	450.00
2	TO REMOVE DASHBOARD TO FACILITATE REPAIR	New	280.00	250.00
3	LABOUR CHARGES TO REPLACE ABOVE PARTS	New	800.00	600.00
4	TOWING FEES	New	60.00	50.00
5	TO CHECK WIRING	New	20.00	20.00
			Gross Labour Cost (\$)	1,660.00
				1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >