

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008757/AQCN2**Date:** 25/03/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00090332000

Claimant Vehicle No : YP8326C **Insured Vehicle No :** YN7186G

Date of Loss: 10/08/2021 Nature of Claim: TP Claim No: SNM21D204599/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP8326C**

Make & Model: MITSUBISHI CANTER, 3.0 D (M) Engine No: 4P10C30035

Reg. Date: 29/12/2017 (Man. Year: 2016) Chassis No: FEB50545204

Colour: White Odometer: 80430 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/75R16 Rear Tyre Size: 205/75R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 13,447.94 | 3,345.10 | 10,102.84 | 75.13 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,320.00 | 940.00 | 2,380.00 | 71.69 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 16,767.94 | 4,285.10 | 12,482.84 | 74.44 |
| Approved Total (Overridden) (S\$) | | 3,400.00 | | |
| (S\$) | 16,767.94 | 3,400.00 | 13,367.94 | 79.72 |
| + GST 7.00/7.00% (S\$) | 1,173.76 | 238.00 | 935.76 | 79.72 |
| Nett Amount (S\$) | 17,941.70 | 3,638.00 | 14,303.70 | 79.72 |

INSPECTION

Date of Assignment: 15/10/2021

Date Inspected: 04/10/2021 Inspected At: XINHUA WORKSHOP - KAKI BUKIT (HQ)
23 KAKI BUKIT AVENUE 4, #04-01 (SOUTH WING)
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

| | | |
|----------------------|--|---|
| Reference | | |
| Part Source: | (Last Synchronised: 24 Mar 2022) | |
| Parts: | N/A | mitsubishi canter 3.0 D (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for YP8326C) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Bent | 1,491.38 FL | *1,290.00 FL |
| 2 | 1 | | *FRONT BUMPER SIDE GARNISH RH | Cut | 347.11 FL | *347.11 FL |
| 3 | 1 | | *HEADLAMP RH | Cracked | 876.31 FL | *635.00 FL |
| 4 | 1 | | *HEADLAMP LOWER GARNISH RH | Not Necessary | 49.58 FL | *- FL |
| 5 | 1 | | *HEADLAMP SIDE COVER RH | Cracked | 116.31 FL | *116.31 FL |
| 6 | 1 | | *SIGNAL LAMP RH | Cracked | 424.66 FL | *220.00 FL |
| 7 | 1 | | *REAR VIEW MIRROR | Damaged | 101.69 FL | *101.69 FL |
| 8 | 1 | | *REAR VIEW MIRROR STAY | Bent | 475.02 FL | *475.02 FL |
| 9 | 1 | | *REAR VIEW MIRROR STAY TOP COVER | Not Necessary | 23.38 FL | *- FL |
| 10 | 1 | | *FRONT GRILLE | Not Necessary | 892.79 FL | *- FL |
| 11 | 1 | | *FRONT GRILLE LOGO | Not Necessary | 104.31 FL | *- FL |
| 12 | 1 | | *FRONT CORNER PANEL RH | Damaged | 896.41 FL | *475.00 FL |
| 13 | 1 | | *FRONT STEP PANEL GARNISH RH | Not Necessary | 547.32 FL | *- FL |
| 14 | 1 | | *FRONT STEP PANEL GARNISH REFLECTOR RH | Not Necessary | 65.31 FL | *- FL |
| 15 | 1 | | *FRONT DOOR RH | Repair | 2,971.65 FL | *- FL |
| 16 | 1 | | *FRONT DOOR INNER TRIM RH | Not Necessary | 939.67 FL | *- FL |
| 17 | 1 | | *FRONT DOOR OUTER STRIP RH | Not Necessary | 184.62 FL | *- FL |
| 18 | 1 | | *FRONT DOOR ARCED GARNISH RH | Not Necessary | 498.14 FL | *- FL |
| 19 | 1 | | *FRONT DOOR ARCED GARNISH RUBBER RH | Not Necessary | 87.55 FL | *- FL |
| 20 | 1 | | *FRONT DOOR WEATHERSTRIP RH | Not Necessary | 424.82 FL | *- FL |
| 21 | 1 | | *FRONT DOOR INNER LOCK RH | Not Necessary | 744.63 FL | *- FL |
| 22 | 1 | | *FRONT DOOR LOCK CATCH RH | Not Necessary | 55.26 FL | *- FL |
| 23 | 1 | | *FRONT DOOR FRAME WEATHERSTRIP RH | Not Necessary | 329.54 FL | *- FL |
| 24 | 1 | | *FRONT DOOR LIGHT RH | Not Necessary | 68.71 FL | *- FL |
| 25 | 1 | | *FRONT DOOR WINDOW GLASS RH | Not Necessary | 689.00 FL | *- FL |
| 26 | 1 | | *FRONT DOOR POWER WINDOW MOTOR RH | Not Necessary | 746.52 FL | *- FL |
| 27 | 1 | | *FRONT DOOR REGULATOR RH | Not Necessary | 437.88 FL | *- FL |
| 28 | 1 | | *FRONT DOOR GLASS CHANNEL RH | Not Necessary | 194.35 FL | *- FL |
| 29 | 1 | | *SET FRONT BUMPER SIDE GARNISH CLIP RH | Necessary | 60.00 FS | *20.00 FS |
| 30 | 1 | | *FRONT BUMPER STICKER (SPECIAL TYPE) | Necessary | 500.00 FS | *200.00 FS |
| 31 | 1 | | *SET HEADLAMP LOWER GARNISH CLIP | Not Necessary | 60.00 FS | *- FS |
| 32 | 1 | | *SET FRONT GRILLE CLIP | Not Necessary | 40.00 FS | *- FS |
| 33 | 1 | | *FRONT CORNER PANEL RH STICKER (SPECIAL TYPE) | Necessary | 400.00 FS | *80.00 FS |
| 34 | 1 | | *SET FRONT STEP PANEL GARNISH CLIP RH | Not Necessary | 50.00 FS | *- FS |
| 35 | 1 | | *FRONT DOOR SEALANT RH | Not Necessary | 150.00 FS | *- FS |
| 36 | 1 | | *FRONT DOOR RH STICKER (SPECIAL TYPE) | Necessary | 1,000.00 FS | *300.00 FS |
| 37 | 1 | | *SET FRONT DOOR ARCED GARNISH CLIP RH | Not Necessary | 50.00 FS | *- FS |
| 38 | 1 | | *SET FRONT DOOR INNER TRIM CLIP RH | Not Necessary | 50.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 17,143.92 | 4,260.13 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 3,695.98 | 915.03 |
| Total Parts (\$\$) | 13,447.94 | 3,345.10 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO PANEL BEAT,WELD,CUT,ADJUST,KNOCK | New | 1,200.00 | 400.00 |
| 2 | TO PUTTY,SPRAY PAINT,POLISH WAX | New | 1,200.00 | 500.00 |
| 3 | TO SPRAY TUFF COAT | New | 250.00 | 40.00 |
| 4 | CONDUCT WATER TER LEAKAGE TEST | New | 80.00 | 0.00 |
| 5 | REMOVE AND REFIX CUSHION EAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR | New | 150.00 | 0.00 |
| 6 | REFOCUS HEADLAMP BEAM | New | 80.00 | 0.00 |
| 7 | TRANFER FRONT DOOR MECHANISM | New | 120.00 | 0.00 |
| 8 | REMOVE AND REINSTALL WINDOW GLASS | New | 60.00 | 0.00 |
| 9 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC | New | 180.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 3,320.00 | 940.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >