



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 2651X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (N)	GRAZED	541.50	541.50
1	SET FRONT BUMPER CLIPS (N)	NECESSARY	30.00	30.00
1	FRONT BUMPER SIDE RETAINER (N)	NOT NECESSARY	25.00	-
	LESS 10% DISCOUNT		-	-57.15
			596.50	514.35
	<b><u>LABOUR</u></b>			
	LABOR FOR PANEL BEATING,CUT,WELD STRAIGHTEN & REPLACING PARTS ETCS. }		250.00	120.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION. }		30.00	-
			280.00	120.00
	<b>GRAND TOTAL</b>		<b>876.50</b>	<b>634.35</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>500.00</b>

Report Ref No. CS/SMO21008760/Uuf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.