

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008766/BES3Q2
Date: 09/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900264400
Claimant Vehicle No :	FBJ8603G	Insured Vehicle No :	SMR4843J
Date of Loss:	12/08/2021	Nature of Claim:	TP
		Claim No:	2290619167SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ8603G		
Make & Model:	YAMAHA FZ16, 153cc (M)	Engine No:	21CG044206
Reg. Date:	20/11/2014 (Man. Year: 2013)	Chassis No:	ME121C0G1E2044204
Colour:	Blue	Odometer:	62675 km
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,751.91	3,559.94	5,191.97	59.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	500.00	750.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,001.91	4,059.94	5,941.97	59.41
Approved Total (Overridden) (S\$)		2,600.00		

Nett Amount (S\$)	10,001.91	2,600.00	7,401.91	74.00
+ Car Rental (4.0 x S\$31.00/day) (S\$)		124.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		30.00		
Nett Liability (S\$)		2,761.45		
Global Sum Settlement (S\$)		2,760.00		

INSPECTION

Date of Assignment: 20/08/2021

Date Inspected: 20/08/2021

Estimated Period of Repair: 3.0 days

Inspected At: Accident Assist SG (HQ)
24 Sin Ming Lane, #01-94 Mid View City
Singapore 573970

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	186.50 FL	*110.00 FL
2	1		*SET HANDLE GRIP	Cut	76.00 FL	*50.00 FL
3	1		*SET HANDLE BALANCER	Cut	84.00 FL	*50.00 FL
4	1		*SET REAR VIEW MIRROR	Cut	95.00 FL	*95.00 FL
5	1		*STEERING STEM	Necessary	187.00 FL	*130.00 FL
6	1		*CLUTCH LEVER	Broken	96.00 FL	*36.00 FL
7	2		*FRONT FORK	Bent	1,192.80 FL	*620.00 FL
8	1		*FRONT FORK BRACKET	Necessary	220.00 FL	*220.00 FL
9	1		*FRONT FORK CLAMP	Necessary	102.00 FL	*72.00 FL
10	1		*FRONT RIM	Not Damaged	400.40 FL	*- FL
11	1		*FRONT RIM SHAFT	Not Necessary	98.00 FL	*- FL
12	1		*FRONT MUDGUARD	Cut	195.00 FL	*140.00 FL
13	1		*FRONT SIGNAL LIGHT LH	Cut	62.00 FL	*48.00 FL
14	1		*GEAR SHIFT PEDAL	Cut	94.40 FL	*66.00 FL
15	1		*GEAR SHIFT PEDAL BRACKET	Cracked	145.00 FL	*145.00 FL
16	1		*FRONT FOOTREST	Not Damaged	68.80 FL	*- FL
17	1		*FRONT FOOTREST BRACKET	Not Damaged	142.40 FL	*- FL
18	1		*REAR FOOTREST	Broken	53.20 FL	*53.20 FL
19	1		*REAR FOOTREST BRACKET	Broken	117.40 FL	*117.40 FL
20	1		*SIDE STAND	Not Damaged	89.00 FL	*- FL
21	1		*FUEL TANK COWLING LH	Cut	245.00 FL	*150.00 FL
22	1		*HEADLIGHT	Cut	350.00 FL	*245.00 FL
23	1		*HEADLIGHT STAY	Not Damaged	92.00 FL	*- FL
24	1		*HEADLIGHT COWLING	Cut	211.00 FL	*200.00 FL
25	1		*TAILLIGHT	Not Damaged	187.00 FL	*- FL
26	1		*REAR MUDGUARD	Not Damaged	284.00 FL	*- FL
27	1		*SET REAR SIGNAL LIGHT	Not Damaged	124.00 FL	*- FL
28	1		*REAR FAIRING LH	Broken	197.00 FL	*165.00 FL
29	1		*REAR RIM	Not Damaged	486.00 FL	*- FL
30	1		*REAR RIM SHAFT	Not Damaged	102.00 FL	*- FL
31	1		*FRONT FAIRING LH	Cut	154.00 FL	*154.00 FL
32	1		*HEADLAMP ASSY	Repeated	1,212.00 FL	*- FL
33	1		*SET EXHAUST SILENCER	Cut	1,211.00 FL	*750.00 FL
34	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
35	1		*REAR NUMBER PLATE	Bent	40.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT NUMBER PLATE	Cut	40.00 FS	*20.00 FS
37	1		*STEERING CONE BEARING	Necessary	60.00 FS	*45.00 FS
38	1		*FRONT FORK OIL	Necessary	68.00 FS	*20.00 FS
39	1		*REAR TYRE	Not Damaged	120.00 FS	*- FS
40	1		*FRONT TYRE	Not Damaged	100.00 FS	*- FS
41	1		*REAR CARRIER BOX	Cut	350.00 FS	*200.00 FS
42	1		*REAR CARRIER BOX BRACKET	Not Damaged	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,607.90	3,921.60
- List Item Discount on L Items 10.00/10.00% (\$)	855.99	361.66
Total Parts (\$)	8,751.91	3,559.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE /REPLACE DAMAGED PARTS & COMPONENTS	New	400.00	200.00
2	TO CARRY OUT BODY FRAME ALIGNMENT	New	350.00	0.00
3	TO RESPRAY REPLACED & AFFECTED PARTS	New	500.00	300.00
Gross Labour Cost (\$\$)			1,250.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >