

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008767/JES3Q2
Date: 25/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006849
Claimant Vehicle No :	SBU2416L	Insured Vehicle No :	SMS2434P
Date of Loss:	18/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003613

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBU2416L	Engine No:	D16Z61706156
Make & Model:	HONDA CIVIC, 1.5 i-VTEC (A)	Chassis No:	JHMEH95800S002597
Reg. Date:	04/05/1992 (Man. Year: 1991)	Odometer:	542194 km
Colour:	Black		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/45 R15	Rear Tyre Size:	195/45 R15
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,196.00	2,704.00	4,492.00	62.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,450.00	1,630.00	52.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,276.00	4,154.00	6,122.00	59.58
Approved Total (Overridden) (S\$)		3,300.00		

Nett Amount (S\$)	10,276.00	3,300.00	6,976.00	67.89
		+ Car Rental (5.0 x S\$100.00/day) (S\$)	500.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	3,807.45	

INSPECTION

Date of Assignment: 20/08/2021

Date Inspected: 20/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

EVEREST MOTOR GARAGE PTE LTD (HQ)
 25 KAKI BUKIT ROAD 4, #05-80, SINGAPORE 417800
 Singapore 417800

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2021)
Parts:	144	HONDA CIVIC 1.5 i-VTEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBU2416L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,578.00 FL	*850.00 FL
2	1		*FRONT BUMPER SIDE RETAINER N/S	Bent	118.00 FL	*30.80 FL
3	1		*FRONT FENDER N/S	Badly Dented	785.00 FL	*553.90 FL
4	1		*FRONT FENDER INNER SHIELD N/S	Torn	182.00 FL	*145.20 FL
5	1		*N/S HEADLAMP	Cracked	982.00 FL	*509.10 FL
6	1		*N/S FRONT SIDE LAMP	Cracked	180.00 FL	*86.50 FL
7	1		*N/S FRONT SHOCK ABSORBER	Not Necessary	492.00 FL	*- FL
8	1		*N/S FRONT KNUCKLE ARM	Not Necessary	438.00 FL	*- FL
9	1		*N/S FRONT LOWER ARM	Not Necessary	392.00 FL	*- FL
10	1		*N/S FRONT WHEEL BEARING	Not Necessary	278.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL	Repair	850.00 FL	*- FL
12	1		*WINDSCREEN WATER TANK	Not Necessary	180.00 FL	*- FL
13	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*35.00 FS
14	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*35.00 FS
15	1		*N/S FRONT SPORTS RIM	Cut	980.00 FS	*300.00 FS
16	1		*CONTROL ARM AND BUSHING N/S	Bent	210.00 F	*210.00 FN
17	1		*UPPER ARM BALL JOINT N/S	Not Necessary	190.00 F	*- FN
18	1		*MOUNTING LOWER N/S	Torn	140.00 F	*140.00 FN
19	1		*FRONT LOWER ARM N/S	Twisted	392.00 F	*392.00 FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	8,487.00	3,287.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,291.00	435.10
- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00	148.40
Total Parts (\$\$)	7,196.00	2,704.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	1,200.00	520.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	700.00
3	TO REMOVE AND REFIX WIRING AND CHECK ELECTRICAL COMPONENTS AND FOCUS HEADLAMP BEAM	New	50.00	20.00
4	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	150.00	0.00
5	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	60.00
6	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	120.00	30.00
7	TO REMOVE AND REFIX CONDENSOR & RADIATOR AND TOPUP GAS	New	120.00	0.00
8	LABOUR FOR INSTALL CONTROL ARM BUSHING ,UPPER ARM BALL JOINT MOUNTING AND LOWER ARM	New	120.00	120.00
Gross Labour Cost (\$\$)			3,080.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >