

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

14/9/21 1/5 \$3300 confirmed with client

Vehicle No. SBU 2416 L HONDA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYORS ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front Bumper		1578.00	
1	Front Bumper side retainer		118.00	
1	Front Fender		785.00	
1	Front Fender inner shield		182.00	
1	LHS Headlamp		982.00	
1	LHS front side lamp		180.00	
1	LHS Front shock absorber		492.00	X
1	LHS Front knuckle arm		438.00	X
1	LHS Front lower arm		392.00	X
1	LHS Front wheel bearing		278.00	X
1	Front support panel		850.00	X
1	Windscreen water tank		180.00	X
			6455.00	
less 20%			1291.00	20%
			5164.00	
SPECIAL NETT ITEMS				
1 set	Front Fender Inner Shield Clips		60.00	35
1set	Front Bumper clips		60.00	35
1	LHS Front Sports Rim		980.00	300
TOTAL PARTS			6264.00	

not Authorized
all means
20/8/11
4/s \$3300
4 days
take photo after repair

LKK Asher

7- 2175.50
20%
7- 1740.40
S.N- 370.00
L- 1330
3440.4
20%
2752.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle No. SBU 2416 L

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00	520
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	700
3	To remove and refix wiring and check electrical components and focus headlamp beam	50.00	20
4	To remove and replace front undercarriage parts	150.00	11X
5	To conduct full computerised wheel alignment test	120.00	60
6	To provide anti-rust treatment on affected areas	120.00	30
7	To remove and refix condensor & radiator and topup gas	120.00 11	X
	Labour Total :	2960.00	
	TOTAL (PARTS & LABOUR):	9224.00	

Vehicle No

SBU2416L

Honda Civic

QTY	Description	Condition	Repairer's Estimate(S\$)	Surveyor's Adjustment
	Control arm, bushing 1/5	3/4	210.00	✓
	Upper arm ball joint 1/5	1/1	190.00	X
	Mounting lower 1/5	7/8	140.00	✓
	Front Lower Arm 1/5	7/1	392.00	✓
	Labour for install control arm bushing, Upper arm ball joint, mounting and lower arm		120.00	✓
		TOTAL PARTS	1052.00	

P-2917.50

202

P-2334

S.N-370

L-1450

4154

202

3323