

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III21008768/UPA3Q2**Date:** 30/09/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
<b>Claimant Vehicle No :</b>	SJT5709H	<b>Insured Vehicle No :</b>	SHD2370C
Date of Loss:	19/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003671

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJT5709H</b>	Engine No:	CAX320093
Make & Model:	VOLKSWAGEN NEW GOLF, 1.4 AT 5K13G5 (A)	Chassis No:	WVWZZZ1KZAW030639
Reg. Date:	19/10/2009 (Man. Year: 2009)	Odometer:	205272 km
Colour:	Red		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,644.00	6,553.12	9,090.88	58.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	1,630.00	1,880.00	53.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,154.00</b>	<b>8,183.12</b>	<b>10,970.88</b>	<b>57.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,500.00</b>		

<b>Nett Amount (S\$)</b>	<b>19,154.00</b>	<b>6,500.00</b>	<b>12,654.00</b>	<b>66.06</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>Nett Liability (S\$)</b>		<b>6,900.00</b>		

INSPECTION

Date of Assignment: 20/08/2021

Date Inspected: 20/08/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Choo Motor Spray Painter (HQ)  
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit  
Singapore 417883

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2021)
<b>Parts:</b> 144	VOLKSWAGEN NEW GOLF 1.4 AT 5K13G5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJT5709H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER SPORT	Distorted / Torn	1,850.00 F	*1,300.00 FL
2	1		*FRONT BUMPER FOG LAMP O/S	Cracked	620.00 F	*295.00 FL
3	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Cut	485.00 F	*300.00 FL
4	1		*FRONT BUMPER SIDE RETAINERS	O/S Cracked	230.00 F	*62.00 FL
5	1		*FRONT BUMPER PDC SENSOR	Not fitted	235.00 F	*- FL
6	1		*FRONT BUMPER BEAM	Repair	485.00 F	*- FL
7	1		*FRONT BUMPER TOW COVER	Cut	35.00 F	*35.00 FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 F	*48.00 FL
9	1		*FRONT GRILLE	Not Necessary	655.00 F	*- FL
10	1		*HEADLAMP LED O/S	Scratched / Cracked	2,450.00 F	*1,950.00 FL
11	1		*HEADLAMP LOWER BRACKET O/S	Cracked	322.00 F	*145.11 FL
12	1		*FRONT SUPPORT PANEL	Cracked	1,080.00 F	*822.15 FL
13	1		*WIPER WASHER TANK	Deformed	285.00 F	*205.50 FL
14	1		*FRONT FENDER O/S	Buckled	745.00 F	*642.23 FL
15	1		*FRONT FENDER INNER SHIELD O/S	Deformed / Torn	315.00 F	*186.20 FL
16	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
17	1		*FRONT DOOR O/S	Repair	1,285.00 F	*- FL
18	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	850.00 F	*- FL
19	1		*FRONT LOWER ARM O/S	Bent	422.00 F	*399.50 FL
20	1		*FRONT KNUCKLE ARM BEARING O/S	Damaged	285.00 F	*285.00 FL
21	1		*FRONT DRIVE SHAFT O/S	Not Necessary	1,450.00 F	*- FL
22	1		*FRONT SPORT RIM O/S	Dented / Warped	1,200.00 FS	*500.00 FS
23	1		*FRONT TYRE O/S	Not Necessary	250.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,644.00</b>	<b>7,225.69</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	672.57

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Total Parts (\$)</b>	<b>15,644.00</b>	<b>6,553.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRT PDC SENSOR	New	80.00	0.00
3	TO REFILL AIR CON GAS	New	120.00	100.00
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
5	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	180.00	120.00
6	TO SPRAY RUST PROOFING	New	50.00	30.00
7	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	680.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,510.00</b>
				<b>1,630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >