10/1/21, 4:34 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS/CTI21008769/EQCN2 Our File No:

01/10/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00060162106

Claimant Vehicle

SML9436A

Insured

GBB5256L

No:

Vehicle No:

Date of Loss:

18/08/2021

Nature of Claim: TP

Claim

SNM21D204601/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

SML9436A Reg No:

Make & Model:

MERCEDES-BENZ CLA 200, 1.3 SB PROGRESSIVE

Engine No:

27091030294488

Reg. Date:

16/01/2014 (Man. Year: 2013)

Chassis No: Odometer:

WDD1173432N051199

129410 km

Colour: Black 1595 cc

Engine Capacity:

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 225/40 R18 Rear Tyre Size: Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm Front Right Side: Rear Right Side: Goodyear 4 mm Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,748.41	3,773.86	10,974.55	74.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,040.00	2,510.00	70.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,298.41	4,813.86	13,484.55	73.69
+ GST 7.00/7.00% (S\$)	1,280.89	336.97	943.92	73.69
Nett Amount (S\$)	19,579.30	5,150.83	14,428.47	73.69

INSPECTION

Date Inspected:

20/08/2021 Date of Assignment:

> 20/08/2021 Inspected At:

Accord Auto Services Pte Ltd (Bukit Merah)

BLK 1009 BUKIT MERAH LANE 3, #01-80

Singapore 159723

Estimated Period of Repair: 4.0 days

Adjuster: **CHEN TSUE YEE** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/1/21, 4:34 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Oct 2021)

Parts: 143 MERCEDES-BENZ CLA 200 1.3 SB PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SML9436A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	2,658.98 FL	*- FL
2	1		*FRONT RH FENDER	Repair	870.65 FL	*- FL
3	1		*FRONT RH FENDER SHIELD	Not Necessary	268.98 FL	*- FL
4	1		*FRONT BUMPER	Broken	2,250.00 FL	*1,421.95 FL
5	1		*FRONT RH BUMPER SIDE RETAINER	Broken	105.00 FL	*105.00 FL
6	1		*FRONT BUMPER TOP INNER BRACKET	Not Necessary	275.00 FL	*-FL
7	1		*FRONT BUMPER RH INNER BRACKET	Not Necessary	258.00 FL	*-FL
8	1		*FRONT BUMPER RH NOZZLE COVER	Not Necessary	95.00 FL	*-FL
9	1		*FRONT BUMPER RH FOGLAMP GARNISH	Not Necessary	116.85 FL	*-FL
10	1		*FRONT RH BUMPER SENSOR	Not Necessary	280.00 FL	*-FL
11	1		*STEERING RACK	Not Necessary	4,555.00 FL	*- FL
12	1		*FRONT RH HEADLAMP	Broken	2,680.40 FL	*2,632.90 FL
13	1		*FRONT RH HEADLAMP CONTROL UNIT (BIG)	Not Necessary	831.60 FL	*-FL
14	1		*FRONT RH HEADLAMP CONTROL UNIT (SMALL)	Not Necessary	365.00 FL	*-FL
15	1		*FRONT RH HEADLAMP LOWER BRACKET	Not Necessary	110.00 FL	*-FL
16	1		*SET FRONT FENDER SHIELD CLIPS	Not Necessary	70.00 FS	*-FS
17	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
18	1		*SET FRONT UNDER BUMPER COVER CLIPS & UNDER ENG CLIPS	Not Necessary	60.00 FS	*-FS
19	1		*TYRE	Not Necessary	420.00 FS	*- FS
F=Fra	ınchise	part. S=9	SpcNett. L=ListItemDisc.	Cub Total (Of)	40 220 40	4 400 05
			- List Item Discount on L Items 1	Sub Total (S\$) 0.00/10.00% (S\$)	•	4,189.85 415.99

Total Parts (S\$) 14,748.41 3,773.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	SPRAY PAINTING TO ALL AFFECTED AREAS (FRONT RH DOOR)	New	1,000.00	400.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	300.00
3	CHECK WIRING SYSTEM & LIGHT	New	100.00	50.00
4	ANTI RUST TREATMENT	New	120.00	30.00
5	TO CHECK & ADJUST WHEELALIGNMENT	New	100.00	60.00
6	TO REMOVE/REPLACE STEERING RACK	New	500.00	0.00
7	TO REPROGRAMMING HEADLAMP CONTROL UNIT	New	380.00	100.00
8	COMPUTER DIAGNOSTIC	New	350.00	100.00
	Gross Labour Cost (S\$)		3,550.00	1,040.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >