

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21008771/KQCN2**Date:** 01/10/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00067272102

**Claimant Vehicle No :** SMC807U **Insured Vehicle No :** GBH5530M

Date of Loss: 19/08/2021 Nature of Claim: TP Claim No: SNM21D204618/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC807U**

Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4430958

Reg. Date: 26/06/2018 (Man. Year: 2017) Chassis No: RU11230951

Colour: Metallic Dark Grey Odometer: 90525 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16

Front Left Side: Sumitomo 9 mm Rear Left Side: Sumitomo 9 mm

Front Right Side: Sumitomo 9 mm Rear Right Side: Sumitomo 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,608.00	3,463.00	1,145.00	24.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	2,020.00	620.00	23.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,248.00</b>	<b>5,483.00</b>	<b>1,765.00</b>	<b>24.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>507.36</b>	<b>383.81</b>	<b>123.55</b>	<b>24.35</b>
<b>Nett Amount (S\$)</b>	<b>7,755.36</b>	<b>5,866.81</b>	<b>1,888.55</b>	<b>24.35</b>

INSPECTION

Date of Assignment: 29/09/2021

Date Inspected: 20/08/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 30 Sep 2021)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMC807U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	190.00 FS	*190.00 FS
2	6		*REAR BUMPER CLIPS	Necessary	12.00 FS	*12.00 FS
3	1		*REAR BUMPER LH SIDE RETAINER	Distorted	12.00 FS	*12.00 FS
4	1		*REAR END PANEL	Repair	290.00 FS	*- FS
5	1		*REAR END PANEL INNER TOP GARNISH	Distorted	48.00 FS	*48.00 FS
6	1		*TAILGATE	Bent	620.00 FS	*620.00 FS
7	1		*TAILGATE EMBLEM (VEZEL)	Necessary	30.00 FS	*30.00 FS
8	1		*TAILGATE INNER LOCK	Jammed	70.00 FS	*70.00 FS
9	1		*TAILGATE INNER RUBBER	Distorted/Dented	50.00 FS	*50.00 FS
10	1		*TAILGATE OUTER GARNISH	Cracked	210.00 FS	*210.00 FS
11	2		*TAILGATE REFLECTORS	Cracked	290.00 FS	*290.00 FS
12	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	70.00 FS	*70.00 FS
13	1		*REAR WINDSCREEN GLASS	Shattered	520.00 FS	*520.00 FS
14	1		*REAR WIPER ARM	Broken	48.00 FS	*48.00 FS
15	1		*REAR WIPER MOTOR	Jammed	110.00 FS	*110.00 FS
16	1		*REAR WIPER ARM COVER	Missing	8.00 FS	*8.00 FS
17	1		*REAR SPARE COMPARTMENT	Repair	320.00 FS	*- FS
18	1		*REAR SPARE TYRE TOP BOARD	Serviceable	155.00 FS	*- FS
19	1		*REAR TOOL BOX	Cracked	110.00 FS	*110.00 FS
20	1		*REAR LH FENDER INNER GARNISH	Buckled/Distorted	290.00 FS	*290.00 FS
21	2		*TAILLAMPS	Cracked	500.00 FS	*500.00 FS
22	1		*REAR WIPER BLADE	Broken	35.00 FS	*35.00 FS
23	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
24	1		*SET CCTV CAMERA	Serviceable	380.00 FS	*- FS
25	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>4,608.00</b>	<b>3,463.00</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE & REFIX REAR SEAT,CARPET,GARNISH,ETC	New	100.00	100.00
3	REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,TAILGATE & ATTACHMENT,TO STRAIGHTEN,KNOCK & REPAIR REAR LH FENDER & CHASSIS,CUT,WELD & RENEW REAR COMPARTMENT,REAR END PANEL	New	1,200.00	800.00
4	PUTTY & RESPRAY ON REAR COMPARTMENT,REAR END PANEL,REAR BUMPER,TAILGATE,OUTER GARNISH,REAR FENDERS & REAR AFFECTED AREAS	New	1,100.00	900.00
5	RUSTPROOFING	New	80.00	60.00
6	REMOVE & REFIX REAR CCTV CAMERA,SMART KEY SENSOR & RESET SYSTEM	New	60.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>2,640.00</b>	<b>2,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >