

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 2525U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED / DENTED	2,190.00	1,831.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	735.00	-
1	REAR BUMPER LOWER GRILLE	DENTED	295.00	295.00
1	REAR BUMPER LOWER LIP COVER	CRACKED	290.00	290.00
1	REAR BUMPER INNER BRACKET LH	CRACKED	65.00	65.00
1	REAR BUMPER INNER BRACKET RH	CRACKED	65.00	65.00
1	REAR BUMPER CENTER RETAINER	CRACKED	105.00	105.00
2	REAR BUMPER REVERSE SENSOR @\$195.00	DENTED	390.00	390.00
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-413.50	-304.10
			3,721.50	2,736.90
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
			60.00	60.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR END PANEL.		700.00	220.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER,REAR BUMPER LOWER LIP COVER,REAR END PANEL & ETC.		700.00	250.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.		120.00	60.00
	TO DIAGNOSIS FAULT CODE & RESET MEMORY.		120.00	30.00
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		100.00	15.00
			1,740.00	575.00
	GRAND TOTAL		5,521.50	3,371.90

Report Ref No. CS/AGI21008779/Kuf3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI21008779/Kuf3n2

KONG SENG CHEONG

Licensed Appraiser