

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Reg. No: 19960/198R GST Reg. No. 19-960/198-R | | | | | |
|---|---|--|-----------------|--------------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | Ref | f: CS/AGI21008779/Kuf3n2 | |
| | (BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924 | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | Da | te: 14/10/2021 | |
| | | | Co | de: AGI | |
| 1. | • | | | | |
| | Insured Veh. | SGC 405S | Veh. Inspected | SMC 2525U | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | C10011350/CD | Excess (\$) | 0.00 | |
| | Assign From | IVY RATILLA | Assign Date | 20/08/2021 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | MERCEDES C200 (A) | c.c | 1991 | |
| | Engine No. | HIDDEN | Year of Reg. | 2018 | |
| | Chassis No. | WDD2050422R329682 | Colour | WHITE | |
| | Odometer | 59449 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| | General | GOOD | | | |
| 3. | Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 225/45 R18 | ROADSTONE | 8 mm | |
| | L/H Front Tyre | 225/45 R18 | ROADSTONE | 8 mm | |
| | R/H Rear Tyre | 245/40 R18 | BRIDGESTONE | 6 mm | |
| | L/H Rear Tyre | 245/40 R18 | BRIDGESTONE | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 20/08/2021 | Inspection Date | 23/08/2021 | |
| | Survey held at | OPTIMA WERKZ PTE LTD | | | |
| | | 9A SERANGOON NORTH AVE 5 SINGAPORE 554500 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: