



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KITTY			Ref: CC4/ASM19001898/Rpa3q2 Date: 15/08/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLA 1874R	Veh. Inspected	PZ 955T	
Policy No.	GA092428	Coverage (\$)	0.00	
Claim No.	S9M01AKY	Excess (\$)	0.00	
Assign From		Assign Date	29/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER 3.0	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KDH2230020899	Colour	WHITE	
Odometer	287116 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	ATLAS	6 mm	
L/H Front Tyre	195 R15	ATLAS	6 mm	
R/H Rear Tyre	195 R15	ATLAS	6 mm	
L/H Rear Tyre	195 R15	ATLAS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/01/2019	Inspection Date	20/08/2021	
Survey held at	CROWN ASIA BUS BUILDER PTE LTD NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	