



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 4315R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S FRONT DOOR	BENT / WARPED	914.00	914.00
1	N/S FRONT DOOR TOP MOULDING	NOT NECESSARY	125.00	-
1	N/S FRONT DOOR RUBBER	NOT NECESSARY	105.00	-
1	N/S REAR DOOR	DENTED / WARPED	842.00	842.00
1	N/S REAR DOOR TOP MOULDING	NOT NECESSARY	125.00	-
1	N/S REAR DOOR RUBBER	NOT NECESSARY	115.00	-
1	N/S ROCKER PANEL	TO REPAIR SEE LABOUR	1,729.00	-
	LESS 10% DISCOUNT		-395.50	-175.60
			3,559.50	1,580.40
	<u>LABOUR</u>			
	TO RUST-PROOFING OF THE AFFECTED AREAS.		250.00	60.00
	TO TRANSFER OF LEFT BOTH DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST. }		200.00	120.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED. }		80.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF N/S ROCKER PANEL.		750.00	450.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		750.00	580.00
			2,030.00	1,210.00
	GRAND TOTAL		5,589.50	2,790.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,200.00

Report Ref No. CS/AGI21008786/Uuf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.