

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21008789/AVCE2

Date: 11/10/2021

REFERENCE

Insured/Claimant:	FOCK YIN LING MRS NG YIN LING	Policy No:	2070121931	
Date of Loss:	14/08/2021	Nature of Claim:	OD	Claim No: 4909942741SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCN709E	Engine No:	CZD898283
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF32L1118517
Reg. Date:	22/08/2020 (Man. Year: 2020)	Odometer:	12315 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,846.00	2,257.00	2,589.00	53.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,032.00	2,432.00	1,600.00	39.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,878.00	4,689.00	4,189.00	47.18
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	8,478.00	4,289.00	4,189.00	49.41
+ GST 7.00/7.00% (S\$)	593.46	300.23	293.23	49.41
Nett Amount (S\$)	9,071.46	4,589.23	4,482.23	49.41

INSPECTION

Date of Assignment:	23/08/2021		
Date Inspected:	20/08/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Client withdraw his own policy claim.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$250.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,634.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	211.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	459.00 FS	*459.00 FS
4	1		*REAR BUMPER BRACKET	Not Necessary	48.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR	Not Necessary	41.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	63.00 FS	*- FS
7	2		*REAR WHEEL ARCH COVER - LH / RH	O/S Cut / N/S Necessary	536.00 FS	*536.00 FS
8	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	241.00 FS	*- FS
9	1		*REAR WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	101.00 FS	*- FS
10	1		*REAR ALUMINIUM RIM - RH	Cut	1,262.00 FS	*1,262.00 FS
11	1		*SUNDRIES	* Check	250.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					4,846.00	2,257.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	2,000.00	1,100.00
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			4,032.00	2,432.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >