

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC21008792/R1tf3e2
	300 BEACH ROAD SINGAPORE 1995		Date:	25/08/2021	
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XD 2876X	Veh. Inspected		XD 5222M
	Policy No.	olicy No. Coverage (\$)			0.00
	Claim No.	20/21/21/VC06/024866	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		23/08/2021
2.	Vehicle Particulars & Condition				
	Make & Model	ISUZU CYZ52K	c.c		15681
	Engine No.	HIDDEN	Year of Reg.		2011
	Chassis No.	JALCYZ52KB7000054	Colour		WHITE
	Odometer	666983 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	295/80 R22.5	FIREMAX		8 mm
	L/H Front Tyre	295/80 R22.5	FIREMAX		8 mm
	R/H Rear Tyre	295/80 R22.5 (D/D)	FIREMAX		8/8/8/8 mm
	L/H Rear Tyre	295/80 R22.5 (D/D)	FIREMAX		8/8/8/8 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S FRONT PORTION.			
5.	General Information				
	Accident Date	19/08/2021	Inspect Date / 7	Гіте	23/08/2021 (02:55 PM)
	Survey held at	TONG HENG MOTOR WORKS			
		BLK 6 KRANJI ROAD #01-26 SINGAPORE 739542			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21008792/R1tf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser