

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21008793/UTF3E2

Date: 27/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993666		
Claimant Vehicle No :	SJK6462J	Insured Vehicle No :	XE4566Y		
Date of Loss:	18/08/2021	Nature of Claim:	TP	Claim No:	1995075481SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK6462J	Engine No:	3ZZ4804582
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106121425
Reg. Date:	29/10/2008 (Man. Year: 2008)	Odometer:	272734 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/08/2021	
Date Inspected:	23/08/2021 Inspected At:	Huat Automobile Air-con Service (HQ) 3007 Ubi Road 1 #01-404, Kampong Ubi Industrial Estate Singapore 408701
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$42,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER O/S	Badly Dented	0.00 F	*- F
2	1		*FRONT FENDER INNERSHIELD O/S	Torn	0.00 F	*- F
3	1		*SET FRONT FENDER INNERSHIELD CLIP O/S	Necessary	0.00 F	*- F
4	1		*FRONT FENDER VVTI EMBLEM O/S	Necessary	0.00 F	*- F
5	1		*FRONT DOOR O/S	Badly Dented	0.00 F	*- F
6	1		*FRONT DOOR OUTER MIRROR ASSY O/S	Broken	0.00 F	*- F
7	1		*FRONT DOOR OUTER PROTECTOR O/S	Distorted	0.00 F	*- F
8	1		*FRONT DOOR GLASS OUTER MOULDING O/S	Bent	0.00 F	*- F
9	1		*FRONT DOOR INNER LOCK O/S	Jammed	0.00 F	*- F
10	1		*FRONT DOOR INNER TRIM BOARD O/S	Deformed / Torn	0.00 F	*- F
11	1		*FRONT DOOR INNER RUBBER O/S	Necessary	0.00 F	*- F
12	2		*FRONT DOOR HINGES O/S	Twisted	0.00 F	*- F
13	1		*FRONT DOOR CHECKER O/S	Bent	0.00 F	*- F
14	1		*FRONT DOOR OUTER HANDLE O/S	Cut	0.00 F	*- F
15	1		*FRONT DOOR OUTER HANDLE EYE KNOCK O/S	Cut	0.00 F	*- F
16	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Necessary	0.00 F	*- F
17	1		*FRONT DOOR GLASS REGULATOR & MOTOR O/S	Bent / Jammed	0.00 F	*- F
18	1		*REAR DOOR O/S	Badly Dented	0.00 F	*- F
19	1		*REAR DOOR GLASS OUTER MOULDING O/S	Bent	0.00 F	*- F
20	1		*REAR DOOR OUTER PROTECTOR O/S	Distorted	0.00 F	*- F
21	1		*REAR DOOR INNER LOCK O/S	Jammed	0.00 F	*- F
22	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed / Torn	0.00 F	*- F
23	1		*REAR DOOR INNER RUBBER O/S	Necessary	0.00 F	*- F
24	1		*REAR DOOR OUTER HANDLE O/S	Cut	0.00 F	*- F
25	1		*REAR DOOR FRAME BLACK STICKER O/S	Necessary	0.00 F	*- F
26	1		*REAR DOOR GLASS REGULATOR & MOTOR O/S	Bent / Jammed	0.00 F	*- F
27	1		*REAR FENDER O/S	Badly Dented	0.00 F	*- F
28	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
29	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
30	1		*REAR BUMPER	Distorted	0.00 F	*- F
31	1		*REAR BUMPER SPOILER	Repair	0.00 F	*- F
32	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
33	1		*ROCKER PANEL O/S	Dented	0.00 F	*- F
34	1		*ROCKER PANEL GARNISH OUTER O/S	Torn	0.00 F	*- F
35	1		*ROCKER PANEL GARNISH INNER O/S	Torn	0.00 F	*- F
36	1		*TAILLAMP O/S	Cracked	0.00 F	*- F
37	1		*CENTRE PILLAR O/S	Repair	0.00 F	*- F
38	1		*FRONT SPORT RIM O/S	Cut	0.00 F	*- F
39	1		*O/S DOOR VISOR	Necessary	0.00 F	*- F
40	1		*REAR SPORT RIM O/S	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)0.000.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >