

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21008794/GTF3N2**Date:** 22/10/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : C001377453 **Insured Vehicle No :** GBA5601D
 Date of Loss: 23/07/2021 Nature of Claim: TP Claim No: 1870964675SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **C001377453**
 Make & Model: MASERATI GHIBLI, 3.0 (A) Engine No: HIDDEN
 Reg. Date: (Man. Year:) Chassis No: ZAMAS57C001377453
 Colour: White Odometer: 66 km
 Engine Capacity: 0 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
 Front Left Side: Continental 9 mm Rear Left Side: Continental 9 mm
 Front Right Side: Continental 9 mm Rear Right Side: Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,524.53	7,146.63	3,377.90	32.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	620.00	2,200.00	78.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,344.53	7,766.63	5,577.90	41.80
Approved Total (Overridden) (S\$)		6,200.00		
Nett Amount (S\$)	13,344.53	6,200.00	7,144.53	53.54

INSPECTION

Date of Assignment: 23/08/2021
 Date Inspected: 23/08/2021 Inspected At: Hup Ley Huat Motor Spray Painting Services
 BLK 1 KAKI BUKIT AVE 6 #01-35
 Singapore 409793
 Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,069.10 F	*3,069.10 FL
2	1		*FRONT BUMPER BRACKET	Not Necessary	55.00 F	*- FL
3	1		*FRONT HEADLAMP	Cut	4,871.60 F	*4,871.60 FL
4	1		*FRONT BUMPER PARKING SENSOR	Not Necessary	1,418.83 F	*- FL
5	1		*FRONT GRILLE ASSEMBLY	Not Necessary	789.80 F	*- FL
6	1		*FRONT LOWER GRILLE	Not Necessary	320.20 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	10,524.53	7,940.70
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	794.07
Total Parts (\$)	10,524.53	7,146.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TUFF COAT AFFECTED AREAS	New	120.00	0.00
2	TO SPRAY PAINT INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS,REPAIR BODY PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	300.00
3	TO PROVIDE LABOUR CHARGES,WORKMANSHIP TO RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	250.00
4	TO REMOVE AND REFIT,WIRING FOR FRONT SENSOR	New	150.00	40.00
5	TO FOCUS HEADLAMP	New	150.00	30.00
Gross Labour Cost (\$)			2,820.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >