

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21008797/VQF3N2**Date:** 10/09/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** GBD2456K**Insured Vehicle No :** SMR4116A

Date of Loss: 04/08/2021

Nature of Claim: TP

Claim No: 1095103661SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBD2456K**

Make &amp; Model: TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)

Engine No: 1KD2414175

Reg. Date: 15/08/2014 (Man. Year: 2014)

Chassis No: KDY2318016275

Colour: Silver

Odometer: 140271 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/75R15

Rear Tyre Size: 165R13C

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 23/08/2021

Date Inspected: 02/09/2021 Inspected At:

Hup Ley Huat Motor Spray Painting Services

BLK 1 KAKI BUKIT AVE 6 #01-35

Singapore 409793

Estimated Period of Repair: 3.0 days

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$33,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Dented	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Dented	0.00 F	*- F
3	1		*REAR BUMPER STEP PANEL	Dented	0.00 F	*- F
4	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
5	1		*TAILGATE	Dented	0.00 F	*- F
6	1		*TAILGATE HINGE	Bent	0.00 F	*- F
7	2		*13PAX & 70KM/H	Necessary	0.00 F	*- F
8	1		*STICKER DYNA	Necessary	0.00 F	*- F
9	1		*STICKER PANDUIT	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >