



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTY 2878

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	UPPER BRACKET (CONSISTENT)	BENT	295.00	295.00
1	CON BEARING (CONSISTENT)	NECESSARY	95.00	95.00
1	HANDLE BAL (CONSISTENT)	BENT	145.00	145.00
1	HANDLEBAR BALANCER (CONSISTENT)	CUT	58.00	58.00
1	MIRROR (CONSISTENT)	BROKEN	96.00	96.00
1	BRAKE PUMP (CONSISTENT)	CRACKED	185.00	185.00
1	BRAKE LEVER (CONSISTENT)	CUT	38.00	38.00
1	TOP COWLING (CONSISTENT)	CUT	98.00	98.00
1	FRONT COWLING COVER (CONSISTENT)	CUT	125.00	125.00
1	FRONT BLACK COVER (CONSISTENT)	CUT	135.00	135.00
1	FENDER COWLING COVER (CONSISTENT)	CUT	135.00	135.00
1	FENDER BLACK COWLING COVER (CONSISTENT)	CUT	125.00	125.00
1	KBY FENDER BLACK COVER (CONSISTENT)	CUT	165.00	165.00
1	BASKET (CONSISTENT)	DEFORMED	38.00	38.00
1	FRONT FENDER LBD LIGHT (CONSISTENT)	CUT	230.00	230.00
1	FRONT MUDGUARD (CONSISTENT)	CUT	98.00	98.00
1	FRONT SPORT RIM (CONSISTENT)	NOT NECESSARY	295.00	-
1	FRONT NO PLATE (CONSISTENT)	NECESSARY	28.00	28.00
1	FRONT DISKBRAHE (CONSISTENT)	NOT NECESSARY	135.00	-
1	FRONT BRAKECALIPER BRAKE (CONSISTENT)	CUT	115.00	115.00
1	SIDE COVER R (CONSISTENT)	CUT	145.00	145.00
1	SIGNAL LIGHT R (CONSISTENT)	CUT	98.00	98.00
1	LOW BLACK COVER R (CONSISTENT)	CUT	78.00	78.00
1	CLUTCH ENGINE COVER (CONSISTENT)	CUT	165.00	165.00
1	EXHAUST PIPE ASSY (CONSISTENT)	BENT	390.00	390.00
2	EXHAUST PIPE COVER (CONSISTENT)	CUT	85.00	85.00
1	FOOT LESS FRONT (CONSISTENT)	DENTED	95.00	95.00
1	FOOT LESS BRACKET (CONSISTENT)	BENT	85.00	85.00
1	BRAKE PENDER (CONSISTENT)	BENT	98.00	98.00
1	PILLION FOOT LESS (CONSISTENT)	CUT	48.00	48.00
1	PILLION FOOT LESS BRACKET R (CONSISTENT)	DENTED	95.00	95.00

Report Ref No. CC4/ASM21008798/T1ra3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SIDE COVER R (CONSISTENT)	CUT	135.00	135.00
1	REAR PILLION HANDLE GRIP BAR (CONSISTENT)	CUT	85.00	85.00
1	REAR SIGNAL LIGHT R (CONSISTENT)	CUT	48.00	48.00
1	REAR MUDGUARD (CONSISTENT)	CUT	78.00	78.00
1	REAR NO PLATE (CONSISTENT)	BENT	28.00	28.00
	LESS 10% DISCOUNT		-	-396.00
			4,390.00	3,564.00
	<u>SPECIAL NETT ITEMS</u>			
1	TOWING-TP-POLICE (SN) (CONSISTENT)	NECESSARY	45.00	45.00
1	FRONT FORK REPAIR (SN) (CONSISTENT)	SHIFTED	180.00	120.00
			225.00	165.00
	<u>LABOUR</u>			
	LABOUR .		280.00	200.00
			280.00	200.00
	GRAND TOTAL		4,895.00	3,929.00

RECOMMENDED COST OF REPAIRS			3,929.00
------------------------------------	--	--	-----------------

Report Ref No. CC4/ASM21008798/T1ra3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.