

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21008799/AQCE2

**Date:** 05/11/2021

### REFERENCE

Insured/Claimant: LIM THOU YEE Policy No: 1800052485  
Date of Loss: 18/08/2021 Nature of Claim: OD Claim No: 3268738536SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA4427S**  
Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK061652  
Reg. Date: 07/06/2018 (Man. Year: 2018) Chassis No: WAUZZZF54JA099662  
Colour: Blue Odometer: 63200 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$131,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	67,807.00	29,013.04	38,793.96	57.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,364.00	12,574.00	15,790.00	55.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>96,171.00</b>	<b>41,587.04</b>	<b>54,583.96</b>	<b>56.76</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>6,731.97</b>	<b>2,911.09</b>	<b>3,820.88</b>	<b>56.76</b>
<b>Nett Amount (S\$)</b>	<b>102,902.97</b>	<b>44,498.13</b>	<b>58,404.84</b>	<b>56.76</b>

### INSPECTION

Date of Assignment: 23/08/2021  
Date Inspected: 20/08/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 15.0 days

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	72.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	228.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	126.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	2,326.00 FS	*1,860.80 FS
8	2		*RADIATOR GRILLE SENSOR SUPPORT - LH / RH	Damaged	102.00 FS	*81.60 FS
9	1		*RADIATOR GRILLE COVER - UPPER	Cracked	189.00 FS	*150.80 FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	948.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	124.00 FS	*99.20 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	845.00 FS	*675.60 FS
13	2		*FRONT BUMPER BRACKET LH / RH	Not Necessary	428.00 FS	*- FS
14	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	72.00 FS	*- FS
15	1		*FRONT BUMPER TOP COVER	Distorted	127.00 FS	*101.60 FS
16	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
17	1		*A/C STICKER	Necessary	8.00 FS	*5.68 FS
18	1		*FRONT LOCK CARRIER UPPER BRACKET	Cracked	137.00 FS	*109.60 FS
19	2		*FRONT LOCK CARRIER LOWER BRACKET - LH / RH	Necessary	58.00 FS	*44.96 FS
20	2		*HORN LH / RH	Not Necessary	252.00 FS	*- FS
21	2		*HORN BRACKET - LH / RH	Not Necessary	58.00 FS	*- FS
22	2		*FRONT PARKING AID SENSOR - INNER (NPA)	Not Necessary	0.00 FS	*- FS
23	1		*FRONT PARKING AID SENSOR SEAL RING - INNER	Not Necessary	510.00 FS	*- FS
24	1		*FRONT FENDER LH / RH	N/S Repair / O/S Buckled	2,120.00 FS	*848.00 FS
25	2		*FRONT FENDER ATTACHMENT PARTS - LH / RH	Not Necessary	53.00 FS	*- FS
26	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	148.00 FS	*- FS
27	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	70.00 FS	*- FS
28	1		*FRONT FENDER BRACE - LH / RH	O/S Bent	236.00 FS	*94.40 FS
29	2		*FRONT FENDER CHROME TRIM - LH / RH	Necessary	328.00 FS	*261.60 FS
30	2		*FRONT FENDER LONG FLEDGE COVER - LH / RH	Not Necessary	72.00 FS	*- FS
31	1		*FRONT FENDER SHORT FLEDGE COVER - LH / RH	O/S Necessary	32.00 FS	*12.24 FS
32	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	550.00 FS	*- FS
33	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	169.00 FS	*- FS
34	1		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	146.00 FS	*- FS
35	1		*BONNET	Distorted	3,312.00 FS	*2,649.60 FS
36	1		*BONNET ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
37	2		*BONNET HINGE - LH / RH	Bent	838.00 FS	*670.40 FS
38	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	28.00 FS	*21.84 FS
39	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	56.00 FS	*43.84 FS
40	1		*BONNET SOUND ABSORBER	Not Necessary	343.00 FS	*- FS
41	2		*BONNET STRIKER - LH / RH	Not Necessary	100.00 FS	*- FS
42	2		*BONNET LOCK - LH / RH	Not Necessary	427.00 FS	*- FS
43	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS
44	1		*BONNET BOWDEN CABLE COVER - CENTER	Not Necessary	10.00 FS	*- FS
45	1		*BONNET BOWDEN CABLE - CENTER	Bent	58.00 FS	*46.00 FS
46	1		*BONNET RELEASE LEVER	Damaged	14.00 FS	*10.48 FS
47	1		*BONNET LOCK CABLE	Not Necessary	74.00 FS	*- FS
48	1		*PLENUM CHAMBER COVER - CENTER	Not Necessary	97.00 FS	*- FS
49	2		*PLENUM CHAMBER COVER - LH / RH	Not Necessary	144.00 FS	*- FS
50	2		*LED HEADLIGHT - LH / RH	Cracked	15,804.00 FS	*12,643.20 FS
51	1		*LED HEADLIGHT POWER MODULE - LH	Not Necessary	758.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*LED HEADLIGHT CONTROL UNIT - LH	Not Necessary	751.00 FS	*- FS
53	1		*LED HEAT SINK - LH	Not Necessary	1,153.00 FS	*- FS
54	1		*LED HEADLIGHT HOSE - LH	Not Necessary	36.00 FS	*- FS
55	2		*LIFT CYLINDER - LH / RH	Not Necessary	396.00 FS	*- FS
56	1		*LIFT CYLINDER HOSE	Not Necessary	86.00 FS	*- FS
57	1		*LOCK CARRIER	Cracked	1,016.00 FS	*812.80 FS
58	2		*LOCK CARRIER RADIATOR LOWER SUPPORT LH / RH	Not Necessary	152.00 FS	*- FS
59	1		*A/C CONDENSOR	Dented	622.00 FS	*497.60 FS
60	1		*A/C PRESSURE SENDER	Not Necessary	186.00 FS	*- FS
61	1		*A/C REFRIGERANT LINE	Not Necessary	167.00 FS	*- FS
62	1		*A/C REFRIGERANT LINE	Not Necessary	340.00 FS	*- FS
63	1		*A/C REFRIGERANT LINE	Not Necessary	248.00 FS	*- FS
64	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Cracked	19.00 FS	*14.56 FS
65	1		*CHARGE AIR COOLER	Not Necessary	587.00 FS	*- FS
66	1		*CHARGE AIR COOLER PRESSURE HOSE	Not Necessary	357.00 FS	*- FS
67	1		*CHARGE AIR COOLER PRESSURE PIPE	Not Necessary	427.00 FS	*- FS
68	1		*RADIATOR	Warped	904.00 FS	*722.80 FS
69	2		*RADIATOR UPPER SECURING PIN	Not Necessary	5.00 FS	*- FS
70	2		*RADIATOR LOWER SUPPORT RUBBER BUSH	Not Necessary	25.00 FS	*- FS
71	1		*RADIATOR COOLANT (6PCS)	Necessary	142.00 FS	*113.28 FS
72	1		*RADIATOR FAN RING	Not Necessary	267.00 FS	*- FS
73	1		*RADIATOR FAN WITH CONTROL UNIT	Not Necessary	2,318.00 FS	*- FS
74	2		*RADIATOR AIR DUCT - LH / RH	Cracked	64.00 FS	*49.52 FS
75	2		*RADIATOR AIR DUCT - LH / RH	Cracked	32.00 FS	*25.60 FS
76	1		*RADIATOR AIR DUCT - UPPER	Not Necessary	16.00 FS	*- FS
77	1		*RADIATOR AIR DUCT - LOWER	Damaged	22.00 FS	*17.20 FS
78	1		*ENGINE AIR FILTER	Not Necessary	386.00 FS	*- FS
79	1		*AIR INTAKE DUCT	Not Necessary	22.00 FS	*- FS
80	1		*AIR INTAKE GUIDE - RH	Deformed	53.00 FS	*42.40 FS
81	1		*AIR INTAKE AIR FLOW SENSOR	Not Necessary	567.00 FS	*- FS
82	1		*AIR INTAKE HOSE	Not Necessary	95.00 FS	*- FS
83	1		*AIR INTAKE HOSE COVER	Not Necessary	240.00 FS	*- FS
84	1		*ENGINE CAM MAGNET	Not Necessary	169.00 FS	*- FS
85	1		*TUBE FOR OIL DIPSTICK	Not Necessary	110.00 FS	*- FS
86	1		*COOLANT TOP HOSE WITH QUICK RELEASE COUPLING	Not Necessary	71.00 FS	*- FS
87	1		*COOLANT HOSE WITH QUICK RELEASE COUPLING	Not Necessary	31.00 FS	*- FS
88	1		*COOLANT PIPE	Not Necessary	54.00 FS	*- FS
89	1		*COOLANT HOSE WITH QUICK RELEASE COUPLING	Not Necessary	183.00 FS	*- FS
90	2		*FRONT DOOR CHROME TRIM - LH / RH	Necessary	328.00 FS	*261.60 FS
91	2		*FRONT WINDOW CHROME SLOT SEAL - LH / RH	Not Necessary	798.00 FS	*- FS
92	1		*REAR BUMPER	Deformed	2,504.00 FS	*2,003.20 FS
93	1		*REAR BUMPER FIXING PARTS	Not Necessary	165.00 FS	*- FS
94	1		*REAR BUMPER SECURING STRIP	Not Necessary	223.00 FS	*- FS
95	1		*REAR BUMPER CHROME TRIM	Cut	1,016.00 FS	*812.80 FS
96	2		*REAR BUMPER LIGHT REFLECTOR - LH / RH	Not Necessary	82.00 FS	*- FS
97	2		*LED TAILLIGHT - LH / RH	Not Necessary	2,038.00 FS	*- FS
98	2		*LED TAILLIGHT TRIM - LH / RH	Not Necessary	60.00 FS	*- FS
99	2		*LED LICENSE PLATE LIGHT - LH / RH	Not Necessary	202.00 FS	*- FS
100	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	940.00 FS	*850.40 FS
101	2		*REAR BUMPER SEAL	Necessary	28.00 FS	*22.40 FS
102	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	46.00 FS	*- FS
103	2		*REAR PARKING AID SENSOR - LH / RH (NPA)	Not Necessary	0.00 FS	*- FS
104	2		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
105	1		*REAR LID	Repair	3,818.00 FS	*- FS
106	2		*REAR LID HINGE LH / RH	Not Necessary	458.00 FS	*- FS
107	1		*REAR LID ATTACHMENT PARTS	Not Necessary	153.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*REAR LID LOCK WITH MICRO SWITCH	Not Necessary	248.00 FS	*- FS
109	1		*REAR LID LOCK COVER	Not Necessary	13.00 FS	*- FS
110	1		*REAR LID GASKET	Not Necessary	236.00 FS	*- FS
111	1		*REAR LID PUSH BUTTON	Not Necessary	1,389.00 FS	*- FS
112	1		*REAR LID STRIKER PLATE	Not Necessary	66.00 FS	*- FS
113	1		*REAR LID PACKING ADHESIVE	Necessary	19.00 FS	*14.88 FS
114	1		*AUDI EMBLEM	Necessary	156.00 FS	*124.40 FS
115	1		*A5 EMBLEM	Necessary	99.00 FS	*79.04 FS
116	1		*TFSI EMBLEM	Necessary	99.00 FS	*79.04 FS
117	1		*REAR WINDSCREEN	Not Necessary	1,168.00 FS	*- FS
118	1		*REAR WINDSCREEN PRIMER	Not Necessary	20.00 FS	*- FS
119	1		*ADDITIONAL BRAKE LIGHT	Not Necessary	576.00 FS	*- FS
120	1		*REAR CROSS PANEL	Repair	356.00 FS	*- FS
121	1		*REAR CROSS PANEL REINFORCEMENT	Repair	632.00 FS	*- FS
122	1		*REAR CROSS PANEL TRIM	Not Necessary	360.00 FS	*- FS
123	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
124	1		*REAR NO PLATE	Dented	60.00 FS	*60.00 FS
125	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
126	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
127	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
128	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
129	1		*SUNDRIES	Necessary	400.00 FS	*81.84 FS
130	1		*ARCYLIX SEALANT	Not Necessary	180.00 FS	*- FS
131	1		*WIRE CONNETOR (Supplementary)	Cracked	9.00 FS	*6.88 FS
132	1		*WIRE CONNETOR (Supplementary)	Cracked	8.00 FS	*5.92 FS
133	1		*HEADLIGHT WASHER BRACKET - LH (Supplementary)	Cracked	15.00 FS	*11.76 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)** **67,807.00**     **29,013.04**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,700.00	1,700.00
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOORS	New	560.00	560.00
5	TO RENEW ENGINE MAGNET AND OTHER ENGINE COMPONENTS	New	480.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	3,000.00
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS	New	6,000.00	3,460.00
8	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
9	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	0.00
10	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	0.00
11	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
12	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	0.00
13	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	480.00	0.00
14	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	750.00
15	TO RESPRAY REAR BUMPER, REAR END PANELLING, SPARE WHEEL HOUSING, REAR LID AND HINGES	New	4,000.00	1,100.00
16	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
17	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
18	TO REMOVE AND RENEW WIRE HARNESS CONNECTOR (Supplementary)	New	280.00	280.00
<b>Gross Labour Cost (\$\$)</b>			<b>28,364.00</b>	<b>12,574.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >