

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21008800/AUCN2**Date:** 13/10/2021**REFERENCE**

Insured/Claimant:	MOHAMAD FIROZ BIN AMAN	Policy No:	7210003361	
Date of Loss:	18/08/2021	Nature of Claim:	OD	Claim No: 3434052074SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX4671G		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC22544
Reg. Date:	14/01/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF3XM1055975
Colour:	White	Odometer:	12927 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R17	Rear Tyre Size:	215/65R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,008.00	2,681.60	3,326.40	55.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,192.00	1,922.00	2,270.00	54.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,200.00	4,603.60	5,596.40	54.87
+ GST 7.00/7.00% (S\$)	714.00	322.25	391.75	54.87
Nett Amount (S\$)	10,914.00	4,925.85	5,988.15	54.87

INSPECTION

Date of Assignment:	20/08/2021		
Date Inspected:	20/08/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Dented	2,816.00 FS	*2,252.80 FS
2	1		*FRONT DOOR OUTER SEAL-RH	Necessary	166.00 FS	*132.80 FS
3	1		*FRONT DOOR CATCH-RH	Not Necessary	120.00 FS	*- FS
4	1		*FRONT DOOR COVER-RH	Necessary	370.00 FS	*296.00 FS
5	1		*FRONT DOOR DATA PLATE FOR TYRE PRESSURE	Not Necessary	30.00 FS	*- FS
6	1		*FRONT WING MIRROR MOUNTING-RH	Not Necessary	2,065.00 FS	*- FS
7	1		*FRONT WING MIRROR MOUNTING CAP-RH	Repair	191.00 FS	*- FS
8	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					6,008.00	2,681.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	400.00	280.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY RHS FRONT DOOR,DOOR COVER AND RHS WING MIRROR COVER	New	2,000.00	950.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,192.00	1,922.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >