



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7623X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RADIATOR GRILLE	SNAPPED	1,409.00	1,409.00
1	FRONT BUMPER MOULDING	SNAPPED	188.00	188.00
1	FRONT BUMPER	DEFORMED	418.30	418.30
1	FRONT BUMPER ABSORBER	SNAPPED	86.90	86.90
1	FRONT BUMPER MOULDING	SNAPPED	93.45	93.45
1	FRONT BUMPER MOULDING UPPER	SNAPPED	188.00	188.00
2	FRONT BUMPER BRACKET RH / LH	DISTORTED	56.00	56.00
2	HEADLAMP RH / LH	SNAPPED	3,987.30	3,987.30
1	FRONT FENDER RH	DENTED	490.70	490.70
1	FRONT FENDER GARNISH RH	MISSING	42.80	42.80
1	FRONT FENDER EMBLEM - BLUE DRIVE RH	NECESSARY	26.60	26.60
2	FRONT DAY LAMP RH / LH	SNAPPED	1,285.00	1,285.00
1	RADIATOR GRILLE COVER	DEFORMED	48.30	48.30
1	HEADLAMP SUPPORT PANEL	SNAPPED	949.30	949.30
1	RADIATOR	DENTED	510.50	510.50
1	RADIATOR INVERTOR	DENTED	884.80	884.80
1	RADIATOR BLOWER	SNAPPED	576.00	576.00
1	A/C CONDENSER	DENTED	663.60	663.60
1	A/C LIQUID TUBE	DENTED	148.50	148.50
2	ACTIVE FLAP	DEFORMED	712.00	712.00
	LESS 20% DISCOUNT		-2,553.01	-2,553.01
			10,212.04	10,212.04
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	CRACKED	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	LABOUR CHARGES.		650.00	640.00
	SPRAY PAINTING CHARGES.		450.00	400.00
	WIRING CHARGES.		30.00	20.00
	TUFF KOTE (WAIVED).	NOT NECESSARY	30.00	-

Report Ref No. CC3/TMI20009057/T1tf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX A/C CONDENSER & REFILL GAS.		120.00	100.00
			1,280.00	1,160.00
GRAND TOTAL			11,542.04	11,422.04
RECOMMENDED COST OF REPAIRS (FRONT)				11,422.04

Report Ref No. CC3/TMI20009057/T1tf3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7623X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF REAR PARTS</u>			
1	REAR BUMPER MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER MOULDING	DEFORMED	47.50	47.50
1	SMART ANTENNA	SNAPPED	40.50	40.50
	LESS 20% DISCOUNT		-107.85	-107.85
			431.40	431.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	CRACKED	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	LABOUR CHARGES.		350.00	320.00
	SPRAY PAINTING CHARGES.		250.00	200.00
			600.00	520.00
	GRAND TOTAL		1,081.40	1,001.40
RECOMMENDED COST OF REPAIRS (REAR)				1,001.40

Report Ref No. CC3/TMI20009057/T1tf3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.