

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21008801/KGA3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900153913-01
<b>Claimant Vehicle No :</b>	SMF7222U	<b>Insured Vehicle No :</b>	SKV3445J
Date of Loss:	17/08/2021	Nature of Claim:	TP
		Claim No:	5898356877SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMF7222U</b>	Engine No:	G4FGJU237321
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU728636
Reg. Date:	23/11/2018 (Man. Year: 2018)	Odometer:	27934 km
Colour:	Dark Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,220.40	1,473.68	746.72	33.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	480.00	200.00	29.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,900.40</b>	<b>1,953.68</b>	<b>946.72</b>	<b>32.64</b>
<b>+ GST 7.00/7.00% (S\$)</b>	203.03	136.76	66.27	32.64
<b>Nett Amount (S\$)</b>	<b>3,103.43</b>	<b>2,090.44</b>	<b>1,012.99</b>	<b>32.64</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,392.44</b>		

INSPECTION

Date of Assignment:	23/08/2021	Ah Lim Motor Company (AMK)
Date Inspected:	23/08/2021 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	3.0 days	

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Bent	1,878.30 FL	*1,782.30 FL
2	2		*REAR DOOR HINGE TOP & LOWER	Repair	91.80 FL	*- FL
3	1		*REAR DOOR CHECKER	Serviceable	47.30 FL	*- FL
4	1		*REAR DOOR POWER WINDOW MOTOR	Serviceable	160.50 FL	*- FL
5	1		*REAR DOOR POWER WINDOW REGULATOR	Serviceable	223.40 FL	*- FL
6	1		*REAR DOOR INNER LOCK	Repair	191.50 FL	*- FL
7	1		*REAR DOOR RUBBER (AT DOOR)	Serviceable	105.80 FL	*- FL
8	1		*REAR DOOR OUTER HANDLE	Dented	59.80 FL	*59.80 FL
9	1		*REAR DOOR OUTER HANDLE SMALL COVER	Serviceable	17.10 FL	*- FL
					<b>Sub Total (\$)</b>	<b>2,775.50      1,842.10</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>555.10      368.42</b>
					<b>Total Parts (\$)</b>	<b>2,220.40      1,473.68</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR /FACILITATE REPAIR	New	80.00	60.00
2	TO DISMANTLE ALL DAMAGED PARTS .TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	300.00	200.00
3	TO SPRAY REAR DOOR RH	New	300.00	220.00
<b>Gross Labour Cost (\$\$)</b>			<b>680.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >