

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008804/AQC�2**Date:** 15/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00142472100
Claimant Vehicle No :	SMU7116P	Insured Vehicle No :	SMM9483H
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	SNM21D204465/C02/SMM9483H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU7116P	Engine No:	L15B6023793
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82103256
Reg. Date:	26/08/2020 (Man. Year: 2019)	Odometer:	23248 km
Colour:	Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,901.92	5,502.64	14,399.28	72.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,760.00	1,570.00	4,190.00	72.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,661.92	7,072.64	18,589.28	72.44
Approved Total (Overridden) (\$\$)		5,600.00		
(\$\$)	25,661.92	5,600.00	20,061.92	78.18
+ GST 7.00/7.00% (\$\$)	1,796.33	392.00	1,404.33	78.18
Nett Amount (\$\$)	27,458.25	5,992.00	21,466.25	78.18

INSPECTION

Date of Assignment:	25/08/2021	
Date Inspected:	24/08/2021 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Sep 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU7116P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP RH	Cut	2,485.00 FL	*2,250.00 FL
2	1		*HEAD LAMP CHROME MOULDING RH	Not Necessary	215.00 FL	*- FL
3	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	141.50 FL	*- FL
4	1		*BONNET SEAL	Not Necessary	84.00 FL	*- FL
5	1		*FRONT SUPPORT TOP GARNISH	Not Necessary	158.00 FL	*- FL
6	1		*FRONT BUMPER	Deformed	1,050.00 FL	*1,050.00 FL
7	1		*FRONT BUMPER SIDE RETAINER	O/s Necessary	197.00 FL	*35.00 FL
8	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	85.00 FL	*- FL
9	1		*FRONT FENDER RH	Dented	468.20 FL	*468.20 FL
10	1		*FRONT FENDER INNER SHIELD LH	Torn	221.10 FL	*221.10 FL
11	1		*FRONT GRILLE CHROME	Not Necessary	485.00 FL	*- FL
12	1		*FRONT GRILLE BASE	Not Necessary	495.00 FL	*- FL
13	1		*FRONT GRILLE LOGO	Not Necessary	121.00 FL	*- FL
14	1		*FRONT GRILLE MOULDING	Not Necessary	154.00 FL	*- FL
15	1		*FRONT ABSORBER RH	Not Necessary	395.20 FL	*- FL
16	1		*FRONT LOWER ARM RH	Not Necessary	260.00 FL	*- FL
17	1		*FRONT KNUCKLE ARM RH	Not Necessary	272.10 FL	*- FL
18	1		*FRONT WHEEL BEARING RH	Not Necessary	184.60 FL	*- FL
19	1		*FRONT DRIVE DRIVE SHAFT	Not Necessary	1,548.00 FL	*- FL
20	1		*FRONT STEERING RACK	Not Necessary	2,254.00 FL	*- FL
21	1		*FRONT DOOR RH	Dented	1,275.00 FL	*1,275.00 FL
22	1		*FRONT DOOR SIDE MIRROR ASSY RH	Damaged	985.00 FL	*754.00 FL
23	1		*FRONT DOOR SIDE MIRROR COVER RH	Repair	67.30 FL	*- FL
24	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	188.90 FL	*- FL
25	2		*FRONT DOOR HINGE RH	Not Necessary	289.80 FL	*- FL
26	1		*FRONT DOOR CHECKER RH	Not Necessary	137.50 FL	*- FL
27	1		*FRONT DOOR OUTER HANDLE RH	Repair	153.70 FL	*- FL
28	1		*FRONT DOOR OUTER HANDLE SIDE COVER RH	Repair	40.00 FL	*- FL
29	1		*FRONT DOOR INNER LOCK RH	Not Necessary	410.80 FL	*- FL
30	1		*FRONT DOOR TRIM WEATHERSTRIP RH	Not Necessary	265.00 FL	*- FL
31	1		*FRONT DOOR LOWER RUBBER SEAL RH	Not Necessary	87.50 FL	*- FL
32	1		*FRONT DOOR CHANNEL RH	Not Necessary	86.70 FL	*- FL
33	1		*FRONT DOOR CHANNEL SEAL RH	Not Necessary	169.70 FL	*- FL
34	1		*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	453.20 FL	*- FL
35	1		*FRONT DOOR REGULATOR GEAR RH	Not Necessary	216.70 FL	*- FL
36	1		*FRONT DOOR INNER TRIM RH	Not Necessary	845.00 FL	*- FL
37	1		*SIDE SKIRT RH	Not Necessary	980.00 FL	*- FL
38	6		*SIDE SKIRT RETAINER	Not Necessary	330.00 FL	*- FL
39	1		*REAR DOOR RH	Repair	899.50 FL	*- FL
40	1		*REAR DOOR RH INNER LOCK	Not Necessary	586.00 FL	*- FL
41	2		*REAR DOOR FRAME BLACK STICKER RH	Not Necessary	160.00 FL	*- FL
42	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	198.00 FL	*- FL
43	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	223.80 FL	*- FL
44	1		*REAR DOOR LOWER RUBBER SEAL RH	Not Necessary	87.50 FL	*- FL
45	1		*REAR DOOR SIDE RUBBER SEAL RH	Not Necessary	98.10 FL	*- FL
46	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT FENDER INNER SHIELD CLIP	Necessary	40.00 FS	*30.00 FS
48	1		*FRONT FENDER SEALANT	Not Necessary	40.00 FS	*- FS
49	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
50	1		*SET FRONT SUPPORT TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
51	1		*FRONT DOOR SEALANT	Not Necessary	60.00 FS	*- FS
52	1		*FRONT DOOR INNER PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
53	1		*FRONT DOOR OUTER PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
54	1		*SET FRONT DOOR INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
55	1		*REAR DOOR INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
56	1		*SET DOOR SUN VISOR	Necessary	600.00 FS	*80.00 FS
57	1		*DOOR SIDE SEAL	Not Necessary	400.00 FS	*- FS
58	1		*SIDE SKIRT CLIP	Not Necessary	60.00 FS	*- FS
59	1		*WHEEL SPORT RIM	Cut	1,200.00 FS	*400.00 FS
60	1		*TYRE	Not Necessary	400.00 FS	*- FS
61	1		*FRONT DOOR FRAME TOP BLACK STICKER RH	Necessary	123.20 FS	*60.00 FS
62	2		*FRONT DOOR FRAME SIDE BLACK STICKER RH	Necessary	152.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	24,003.60	6,713.30
- List Item Discount on L Items 20.00/20.00% (S\$)	4,101.68	1,210.66
Total Parts (S\$)	19,901.92	5,502.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,600.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	250.00	60.00
5	REMOVE AND INSTALL FRONT DOOR PART	New	180.00	80.00
6	REMOVE AND INSTALL REAR DOOR PART	New	180.00	0.00
7	REMOVE AND INSTALL CARPET,SEAT AND INTERIOR	New	450.00	0.00
8	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	650.00	0.00
9	TO CHECK FOUR WHEEL ALIGMENT	New	150.00	0.00
10	ABS SYSTEM LIGHT RESET	New	350.00	0.00
Gross Labour Cost (\$\$)			5,760.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >