

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB21008808/UTF3N2**Date:** 27/09/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SMV3643E**Insured Vehicle No :** SLQ7646J

Date of Loss: 19/08/2021

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMV3643E**

Make & Model: TOYOTA SIENTA 7-SEATER, 1.5 G CVT (A)

Engine No: 1NZR837776

Reg. Date: 28/09/2020 (Man. Year: 2019)

Chassis No: NHP1707194122

Colour: Black

Odometer: 70141 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Rear Tyre Size: 185/60R15

Front Left Side: INTERTRAC 6 mm

Rear Left Side: INTERTRAC 6 mm

Front Right Side: INTERTRAC 6 mm

Rear Right Side: INTERTRAC 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,343.84	4,459.57	12,884.27	74.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	3,080.00	2,870.00	48.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,293.84	7,539.57	15,754.27	67.63
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	23,293.84	6,000.00	17,293.84	74.24

INSPECTION

Date of Assignment: 23/08/2021

Date Inspected: 23/08/2021 Inspected At:

Euro Success Services Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Sep 2021)

Parts: M1-MPV TOYOTA SIENTA 7-SEATER 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMV3643E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR SLIDING DOOR R/H	Badly Dented	1,295.50 FL	*1,295.50 FL
2	2	*REAR DOOR HINGE	Not Necessary	162.00 FL	*- FL
3	1	*REAR DOOR RUBBER R/H	Necessary	150.50 FL	*150.50 FL
4	1	*REAR DOOR OUTER HANDLE R/H	Not Necessary	250.90 FL	*- FL
5	1	*REAR DOOR GLASS OUTER MOULDING R/H	Not Necessary	110.20 FL	*- FL
6	1	*REAR DOOR GLASS RUN CHANNEL R/H	Not Necessary	115.90 FL	*- FL
7	1	*REAR SLIDING DOOR GLASS REGULATOR R/H & MOTOR	Bent/Jammed	330.50 FL	*330.50 FL
8	1	*REAR SLIDING DOOR INNER TRIM BOARD R/H	Deformed/Warped	700.00 FL	*645.10 FL
9	1	*REAR DOOR CHECKER R/H	Not Necessary	72.90 FL	*- FL
10	1	*REAR DOOR CENTRE ROLLER R/H	Twisted	250.00 FL	*245.10 FL
11	1	*REAR DOOR LOWER ROLLER R/H	Twisted	385.90 FL	*188.50 FL
12	1	*REAR DOOR CENTRE LOCK R/H	Jammed	550.70 FL	*409.10 FL
13	1	*REAR SLIDING DOOR R/H	Repeated	1,295.00 FL	*- FL
14	1	*REAR SLIDING DOOR MOTOR R/H	Not Necessary	2,945.10 FL	*- FL
15	1	*REAR FENDER R/H	Badly Dented	1,567.50 FL	*1,071.20 FL
16	1	*REAR INNER FENDER PANEL R/H	Repair	1,350.70 FL	*- FL
17	1	*REAR INNER BOARD R/H	Not Necessary	650.00 FL	*- FL
18	1	*REAR FENDER UPPER COVER	No such part	570.20 FL	*- FL
19	1	*REAR SLIDING DOOR VERTICAL GARNISH NO 1	Necessary	265.80 FL	*110.50 FL
20	1	*REAR SLIDING DOOR VERTICAL GARNISH NO 2	No such part	275.55 FL	*- FL
21	1	*REAR SLIDING DOOR OUTER TOP MOULDING R/H	Not Necessary	175.30 FL	*- FL
22	1	*REAR SLIDING DOOR INNER TRIM R/H	Repeated	790.30 FL	*- FL
23	1	*REAR SLIDING DOOR PROTECTOR R/H	Repeated	562.30 FL	*- FL
24	1	*REAR SLIDING DOOR WINDOW POWER MOTOR	Repeated	970.20 FL	*- FL
25	1	*REAR SLIDING DOOR OUTER PROTECTOR RH	Distorted	215.00 FL	*215.00 FL
26	1	*REAR SLIDING DOOR EDGE MOULDING	Not Necessary	100.00 FL	*- FL
27	1	*REAR AXLE R/H	Not Necessary	2,990.00 FL	*- FL
28	1	*WHEEL BEARING R/H	Not Necessary	520.00 FL	*- FL
29	1	*REAR ABSORBER R/H	Not Necessary	490.00 FL	*- FL
30	1	*REAR ROCKER PANEL RH	Distorted/Cracked	930.50 FL	*845.10 FL
31	1	*REAR FENDER GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
32	1	*REAR DOOR BOARD CLIPS	Necessary	80.00 FS	*40.00 FS
33	1	*REAR TYRE R/H	Serviceable	220.00 FS	*- FS
34	1	*REAR RIM R/H	Bent	800.00 FS	*100.00 FS
35	1	*WHEEL CAP	Cracked	350.00 FS	*150.00 FS
36	1	*REAR FENDER SEALANT R/H	Repeated	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,603.45	5,836.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,259.61	1,376.53
Total Parts (\$\$)	17,343.84	4,459.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER SLIDING DOOR MECHANISM	New	250.00	60.00
2	CHECK WIRING & LIGHTING SYSTEM	New	120.00	20.00
3	REMOVE & REFIX FENDER GLASS	New	200.00	100.00
4	REMOVE & REPLACE & RE-INSTALL REAR INNER TRIMS	New	150.00	80.00
5	TO REMOVE,REPLACE,CUT & WELD THE ABOVE LISTED PARTS	New	2,500.00	1,580.00
6	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	400.00	0.00
7	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
8	TOWING	New	80.00	0.00
9	TOCONDUCT WHEEL ALIGNMENT	New	150.00	60.00
10	TO SPRAY UNDERCOATING	New	300.00	80.00
Gross Labour Cost (\$\$)			5,950.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >