

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21008810/APA3Q2**Date:** 27/12/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMF7790X**Insured Vehicle No :** SJK1157Z

Date of Loss: 18/08/2021

Nature of Claim: TP

Claim No: 5778588228SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMF7790X**

Make &amp; Model: KIA CERATO FORTE KOUP, 1.6 (A)

Engine No: G4FCAH376654

Reg. Date: 22/03/2010 (Man. Year: 2010)

Chassis No: KNAFW611MA5216397

Colour: Black

Odometer: 236784 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,595.01	3,222.35	2,372.66	42.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	1,240.00	2,640.00	68.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,475.01</b>	<b>4,462.35</b>	<b>5,012.66</b>	<b>52.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,475.01</b>	<b>3,500.00</b>	<b>5,975.01</b>	<b>63.06</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,007.45</b>		

INSPECTION

Date of Assignment: 23/08/2021

Date Inspected: 23/08/2021 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)  
13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre  
Singapore 417807

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	910.00 FL	*850.00 FL
2	2		*REAR BOOTLID HINGE LH & RH	Not Necessary	290.40 FL	*- FL
3	1		*REAR BOOTLID LOGO	Necessary	81.00 FL	*81.00 FL
4	1		*REAR BOOTLID INNER LOCK	Damaged	124.30 FL	*124.30 FL
5	1		*REAR BOOTLID WEATHERSTRIP	Cut	320.00 FL	*182.00 FL
6	1		*REAR BUMPER	Deformed	895.00 FL	*614.00 FL
7	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	167.20 FL	*167.20 FL
8	1		*REAR BUMPER INNER SPONGE	Cracked	155.00 FL	*155.00 FL
9	1		*REAR BUMPER LOWER	Deformed	115.00 FL	*115.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	295.00 FL	*295.00 FL
11	2		*REAR BUMPER REINFORCEMENT BRACKET LH & RH	Not Necessary	180.00 FL	*- FL
12	1		*REAR BUMPER TOP & LOWER BRACKET	Not Necessary	220.00 FL	*- FL
13	1		*REAR END PANEL	Dented	510.00 FL	*410.00 FL
14	1		*REAR END PANEL TOP GARNISH	Cracked	120.00 FL	*120.00 FL
15	1		*REAR EXHAUST SILENCER	Not Necessary	980.00 FL	*- FL
16	1		*REAR EXHAUST SILENCER MOULDING	Not Necessary	98.00 FL	*- FL
17	1		*REAR BUMPER REFLECTOR RH	Cracked	78.00 FL	*78.00 FL
18	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
19	1		*SET REAR CAR PLATE WITH HOLDER	Cracked	70.00 FS	*50.00 FS
20	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
21	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
22	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>6,148.90</b>	<b>3,541.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	553.89	319.15
<b>Total Parts (\$)</b>	<b>5,595.01</b>	<b>3,222.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	500.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	500.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	100.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	200.00	60.00
5	TO REMOVE AND REPLACE REVERSE SENSOR AND CHECK FOR PROPER FUNCTION	New	120.00	50.00
6	TO REMOVE AND REFIX REAR WINDSCREEN	New	100.00	100.00
7	TO REMOVE REAR BOOTLID MECHANISM	New	210.00	0.00
8	TO CONDUCT WATER SEEPAGE TEST	New	150.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>3,880.00</b>	<b>1,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >