



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2108719

INV Date 20/12/2021

Reference CC4/LPC21008811/Gpa3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SHB 6188Y  
Insured Veh. XD 9070H  
Claim No. 20/21/21/VC00/024876  
Policy No. Z/20/VC00/108938-001  
Accident Date 21/08/2021  
Inspection Date 23/08/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21008811/Gpa3q2 Date: 20/12/2021 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 9070H	Veh. Inspected	SHB 6188Y	
Policy No.	Z/20/VC00/108938-001	Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024876	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	23/08/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU086651	Colour	BLUE	
Odometer	416812 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/08/2021	Inspection Date	23/08/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6188Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	PANEL ASSY -RR DR RH	BUCKLED	2,201.10	2,201.10
1	PANEL ASSY -FR DR RH	BUCKLED	2,256.40	2,256.40
1	LATCH ASSY -FR DR RH	NOT NECESSARY	490.80	-
1	KEY SUB SET -DOOR RH	DAMAGED	93.25	93.25
1	W/STRIP -FR DR BODY SIDE R	NOT NECESSARY	81.30	-
1	W/STRIP ASSY -FR DR BELT O	NOT NECESSARY	75.40	-
1	MOULDING ASSY -FR DR FRAME	DEFORMED	153.10	153.10
1	HANDLE ASSY -DR O/S	DISTORTED	132.30	132.30
1	COVER -FR DR O/S HDL DRIVE	MISSING	12.60	12.60
1	GLASS -FR DR WINDOW RH	SMASHED	316.30	316.30
1	MIRROR ASSY -RR VIEW O/S R	CRACKED	670.00	670.00
	LESS 20% DISCOUNT		-1,296.51	-1,167.01
			5,186.04	4,668.04
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRT DOOR LOGO SONATA CTPL (SN)	NECESSARY	75.00	75.00
1	APP LOGO REAR DOOR L/R CT (SN)	NECESSARY	80.00	80.00
			155.00	155.00
	<b><u>LABOUR</u></b>			
	TOWING FEE.		60.00	60.00
	PANEL BEATING.		750.00	560.00
	SPRAYPAINT CHARGE.		750.00	500.00
	CHECK ALL LIGHTING.	NOT NECESSARY	50.00	-
	TRANSFER DOOR PART.		120.00	120.00
	RENEW ADVERTISEMENT STICKER -DOOR .		200.00	200.00
			1,930.00	1,440.00
	<b>GRAND TOTAL</b>		<b>7,271.04</b>	<b>6,263.04</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,000.00</b>
---	--	--	-----------------

Report Ref No. CC4/LPC21008811/Gpa3q2

**XING GUO QIANG**

**M.MATAI, AMSAE-A**

**Automotive Assessor**

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 6188Y

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SHB 6188Y**

**RE-INSPECTION**

