

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008814/GPA3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700094958
Claimant Vehicle No :	SHA3695A	Insured Vehicle No :	SLV5078K
Date of Loss:	21/08/2021	Nature of Claim:	TP
		Claim No:	9224120748SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3695A	Engine No:	G4LEKU401788
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU187958
Reg. Date:	07/11/2019 (Man. Year: 2019)	Odometer:	161668 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R18	Rear Tyre Size:	195/65 R18
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,692.32	1,771.76	1,920.56	52.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,610.00	570.00	26.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,872.32	3,381.76	2,490.56	42.41
+ GST 7.00/7.00% (S\$)	411.06	236.72	174.34	42.41

Nett Amount (\$)		6,283.38	3,618.48	2,664.90	42.41
Global Sum Settlement (\$)			0.00		

INSPECTION

Date of Assignment:	23/08/2021			
Date Inspected:	23/08/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969	
Estimated Period of Repair:	5.0 days			

Adjuster:	XING GUO QIANG	Manager:	CHEW HSIAO TONG
------------------	----------------	-----------------	-----------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Repair	1,789.90 FL	*- FL
2	1		*REAR FENDER RH	Buckled	1,768.30 FL	*1,768.30 FL
3	1		*REAR FENDER SHIELD RH	Not Necessary	73.60 FL	*- FL
4	1		*REAR BUMPER	Repair	459.40 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	55.80 FL	*- FL
6	10		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
7	1		*REAR WHEEL CAP RH	Scratched	346.40 FL	*346.40 FL
8	1		*REAR DOOR APPS STICKER RH	Necessary	80.00 FS	*80.00 FS
					Sub Total (S\$)	2,194.70
					- List Item Discount on L Items 20.00/20.00% (S\$)	422.94
					Total Parts (S\$)	1,771.76

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINTING CHARGE	New	900.00	750.00
3	REMOVE/REFIX UPHOLSTERY ETC	New	120.00	60.00
4	R/I REVERSE SENSORS	New	120.00	40.00
5	WHEEL ALIGNMENT	New	120.00	60.00
6	TRANSFER OF DOOR	New	120.00	0.00
Gross Labour Cost (S\$)			2,180.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >