

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008824/DEA3Q2**Date:** 14/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SHA7012U **Insured Vehicle No :** SLM1027G
 Date of Loss: 19/08/2021 Nature of Claim: TP Claim No: MFL2021D0003563

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA7012U**
 Make & Model: HYUNDAI AE IONIQ, 1.6 (A) Engine No: G4LEJU045570
 Reg. Date: 03/07/2018 (Man. Year: 2018) Chassis No: KMHC851CVJU103379
 Colour: Blue Odometer: 296108 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,232.61	17,671.76	6,560.85	27.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,930.00	2,810.00	4,120.00	59.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,162.61	20,481.76	10,680.85	34.27
+ GST 7.00/7.00% (S\$)	2,181.38	1,433.72	747.66	34.27
Nett Amount (S\$)	33,343.99	21,915.48	11,428.51	34.27
+ Loss of Use (10.0 x S\$40.00/day) (S\$)		400.00		
+ Car Rental (10.0 x S\$125.19/day) (S\$)		1,251.90		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		23,654.83		
Global Sum Settlement (S\$)		22,000.00		

INSPECTION

Date of Assignment: 23/08/2021
 Date Inspected: 24/08/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2022)
Parts:	143	HYUNDAI AE IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7012U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID RUBBER	Necessary	187.40 FL	*187.40 FL
3	1		*BOOT LID LOCK UPPER	Not Necessary	224.00 FL	*- FL
4	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
5	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
6	1		*EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
7	1		*BOOT LID LAMP (RH)	Not Necessary	794.40 FL	*- FL
8	1		*BOOT LID TRIMBOARD	Not Necessary	259.70 FL	*- FL
9	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
10	1		*BOOT LID TRIMBOARD CENTRE	Not Necessary	159.60 FL	*- FL
11	1		*BOOT LID TRIMBOARD SIDE (RH)	Not Necessary	92.50 FL	*- FL
12	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
13	1		*BOOT LID GLASS UPPER MOULDING	Serviceable	186.30 FL	*- FL
14	1		*BOOT LID GLASS LOWER MOULDING	Serviceable	145.20 FL	*- FL
15	1		*REAR BUMPER	Torn	459.40 FL	*459.40 FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
17	1		*REAR BUMPER REINFORCEMENT BRACKET (RH)	Cracked	188.10 FL	*188.10 FL
18	1		*REAR BUMPER CENTRE MOULDING ASSY	Dislodged	451.25 FL	*451.25 FL
19	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Dislodged	47.50 FL	*47.50 FL
20	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
21	1		*REAR BUMPER SIDE RETAINER (RH)	Broken	85.80 FL	*85.80 FL
22	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
23	1		*REAR BUMPER UNDER CENTRE	Dislodged	123.85 FL	*123.85 FL
24	1		*REAR BUMPER SIDE UPPER (RH)	Dislodged	123.10 FL	*123.10 FL
25	1		*REAR BUMPER REAR HOOK	Not Necessary	94.60 FL	*- FL
26	2		*REAR BUMPER REFLECTOR LAMP (RH)	Dislodged	165.80 FL	*165.80 FL
27	1		*REAR BUMPER TOWING COVER	Dislodged	98.80 FL	*98.80 FL
28	1		*REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	Dislodged	328.60 FL	*328.60 FL
29	2		*LICENCE LAMP	Dislodged	387.06 FL	*387.06 FL
30	1		*LICENCE LAMP WIRE	Serviceable	135.80 FL	*- FL
31	1		*TAIL LAMP (RH)	Cut / Scratched	870.40 FL	*870.40 FL
32	1		*TAIL LAMP QUARTER PANEL (RH)	Repair	208.90 FL	*- FL
33	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
34	1		*REAR PANEL GARNISH	Not Necessary	346.80 FL	*- FL
35	1		*REAR TRAY TOOLS BOX RH	Not Necessary	675.30 FL	*- FL
36	1		*REAR TRAY LUGGS CENTER	Not Necessary	354.20 FL	*- FL
37	1		*EXHAUST PIPE INSULATOR	Not Necessary	235.00 FL	*- FL
38	1		*EXHAUST SILENCER	Bent	943.50 FL	*943.50 FL
39	1		*EXHAUST PIPE HANGER	Not Necessary	29.20 FL	*- FL
40	1		*REAR FENDER (RH)	Dented	1,768.30 FL	*1,768.30 FL
41	1		*REAR FENDER SHIELD REAR PIECE (RH)	Deformed	173.60 FL	*173.60 FL
42	1		*REAR FENDER SHIELD FRT PIECE (RH)	Not Necessary	165.50 FL	*- FL
43	1		*REAR FENDER AIR-DUCT (RH)	Deformed	87.30 FL	*87.30 FL
44	1		*ASSY BSD BLIND SPOT RADAR (RH)	Damaged / Bent	1,625.00 FL	*1,625.00 FL
45	1		*WIRING HARNESS BWS EXT	Not Necessary	988.90 FL	*- FL
46	1		*REAR TYRE RIM (RH)	Cut	1,124.20 FL	*1,124.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR WHEEL HUP-CAP (RH)	Not fitted	346.40 FL	*- FL
48	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
49	1		*REAR TRAILING ARM (RH)	Bent	265.40 FL	*265.40 FL
50	1		*REAR ASSIST (RH)	Bent	227.90 FL	*227.90 FL
51	1		*REAR SHOCK ABSORBER (RH)	Distorted	230.50 FL	*230.50 FL
52	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	133.10 FL	*- FL
53	1		*REAR ABSORBER STOPPER (RH)	Not Necessary	137.60 FL	*- FL
54	1		*REAR ABSORBER COVER (RH)	Not Necessary	175.60 FL	*- FL
55	1		*REAR CROSSMEMBER	Distorted / Bent	1,468.70 FL	*1,468.70 FL
56	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
57	1		*STABILIZER LINK (RH)	Not Necessary	147.30 FL	*- FL
58	1		*REAR UPPER ARM (RH)	Distorted	239.50 FL	*239.50 FL
59	1		*REAR LOWER ARM (RH)	Distorted	393.10 FL	*393.10 FL
60	1		*REAR KNUCKLE ARM (RH)	Distorted	538.10 FL	*538.10 FL
61	1		*FRT DOOR (RH)	Dented	1,797.20 FL	*1,797.20 FL
62	1		*FRONT DOOR OUTER HANDLE (RH)	Not Necessary	234.80 FL	*- FL
63	1		*FRONT DOOR PROTECTOR (RH)	Necessary	186.20 FL	*186.20 FL
64	1		*REAR DOOR (RH)	Dented	1,789.90 FL	*1,789.90 FL
65	1		*REAR DOOR OUTER HANDLE (RH)	Not Necessary	124.80 FL	*- FL
66	1		*REAR DOOR PROTECTOR (RH)	Necessary	166.20 FL	*166.19 FL
67	1		*ROCKER PANEL OUTER GARNISH	Not Necessary	715.60 FL	*- FL
68	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	35.00 FS	*35.00 FS
69	1		*BOOT LID COMFORT CABLINK TEL NO.STICKER	Not fitted	30.00 FS	*- FS
70	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
71	1		*REAR NO PLATE +TRIM COVER	Dislodged	45.00 FS	*45.00 FS
72	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 FS	*92.00 FS
73	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	120.00 FS	*120.00 FS
74	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
75	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
76	1		*REAR FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
77	1		*REAR TYRE (RH)(50%)	Cut / Punctured	216.00 FS	*108.00 FS
78	1		*FRONT DOOR CITY CAB LOGO (RH)	Not Necessary	75.00 FS	*- FS
79	1		*FRONT DOOR COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
80	1		*FRONT DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
81	1		*REAR DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
82	1		*REAR DOOR TEL NO.STICKER (RH)	Not fitted	10.00 FS	*- FS
83	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
84	1		*ROCKER PANEL OUTER GARNISH ADVERTISEMENT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 29,908.76 21,793.45
- List Item Discount on L Items 20.00/20.00% (\$\$) 5,676.15 4,121.69

Total Parts (\$\$) 24,232.61 17,671.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,000.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,000.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
10	RE-SET REAR ABS SYSTEM	New	400.00	0.00
11	REMOVE/REFIX FUEL TANK	New	80.00	0.00
12	REMOVE/REFIX EXHAUST PIPE	New	80.00	60.00
13	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
14	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
15	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
16	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
17	FOUR WHEEL ALIGNMENT	New	120.00	60.00
18	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	550.00	150.00
19	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR }	New	550.00	0.00
Gross Labour Cost (\$\$)			6,930.00	2,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >