

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21008827/APA3Q2**Date:** 15/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800133760-02
<b>Claimant Vehicle No :</b>	GBK9475Y	<b>Insured Vehicle No :</b>	SKR3288S
Date of Loss:	19/08/2021	Nature of Claim:	TP
		Claim No:	9583338201SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBK9475Y</b>	Engine No:	1GD8617931
Make & Model:	TOYOTA HIACE, 2.8 D DX (A)	Chassis No:	GDH2012014570
Reg. Date:	28/01/2021 (Man. Year: 2020)	Odometer:	18551 km
Colour:	Silver		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,660.50	3,384.25	1,276.25	27.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,610.00	620.00	27.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,890.50</b>	<b>4,994.25</b>	<b>1,896.25</b>	<b>27.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>(S\$)</b>	6,890.50	4,000.00	2,890.50	41.95
<b>+ GST 7.00/7.00% (S\$)</b>	482.34	280.00	202.34	41.95
<b>Nett Amount (S\$)</b>	<b>7,372.84</b>	<b>4,280.00</b>	<b>3,092.84</b>	<b>41.95</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>Nett Liability (S\$)</b>		<b>4,980.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,980.00</b>		

**INSPECTION**

Date of Assignment:	21/08/2021		
Date Inspected:	21/08/2021	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,150.00 FL	*1,855.00 FL
2	1		*TAILGATE LOGO	Necessary	75.00 FL	*75.00 FL
3	1		*TAILGATE TOYOTA HIACE STICKER	Necessary	48.00 FL	*48.00 FL
4	1		*TAILGATE LOCK	Damaged	275.00 FL	*275.00 FL
5	1		*TAILGATE LOCK COVER	Deformed	58.00 FL	*58.00 FL
6	1		*REAR BUMPER	Deformed	615.00 FL	*615.00 FL
7	2		*REAR BUMPER RETAINER	Necessary	200.00 FL	*200.00 FL
8	4		*REAR BUMPER LOWER BRACKETS	Bent	240.00 FL	*80.00 FL
9	6		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
10	1		*END PANEL INNER	Repair	975.00 FL	*- FL
11	1		*END PANEL OUTER	Dented	568.00 FL	*568.00 FL
12	1		*STEP PANEL	Dented	275.00 FL	*275.00 FL
13	1		*SPARE TYRE TRAY	Not Necessary	165.00 FL	*- FL
14	1		*70KM/H STICKER	Necessary	35.00 FS	*15.00 FS
15	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
16	1		*REAR W/SCREEN GUM	Necessary	50.00 FS	*40.00 FS
17	1		*REAR W/SCREEN SEAL	Necessary	30.00 FS	*30.00 FS
18	1		*REAR NO PLATE	Cut	40.00 FS	*40.00 FS
					Sub Total (\$\$)	6,079.00 4,404.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,418.50 1,019.75
					Total Parts (\$\$)	4,660.50 3,384.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,000.00	800.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING	New	30.00	30.00
4	REMOVE & REFIT REAR W/SCREEN	New	120.00	120.00
5	TRANSFER TAILGATE FITTING	New	80.00	60.00
<b>Gross Labour Cost (\$)</b>			<b>2,230.00</b>	<b>1,610.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >