



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 8526U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,855.30	1,180.00
2	REAR BUMPER SIDE RETAINER @\$120.00 (CONSISTENT)	O/S NECESSARY	240.00	120.00
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	NOT NECESSARY	210.30	-
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,553.20	-
	LESS 10% DISCOUNT		-485.88	-130.00
			4,372.92	1,170.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	22.00	22.00
1	WHEEL RIM RH (SN) (CONSISTENT)	CUT	1,400.00	700.00
			1,422.00	722.00
<u>LABOUR</u>				
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		1,000.00	400.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	400.00
	WIRING CHECK .		30.00	30.00
	REMOVE AND REFIX REAR REVERSE SENSOR .		1,000.00	50.00
	FOUR WHEEL ALIGNMENT.		120.00	80.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	250.00	-
			3,400.00	960.00
GRAND TOTAL			9,194.92	2,852.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CC4/ASM21008828/Aps3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.