

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTION RE	PORT		
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21008830/Gvce2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	26/08/2021	
	ATTN: TEO KITTY			Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 3709J	Veh. Inspected	t	FBF 4589L	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03F4E	Excess (\$)		0.00	
	Assign From	TEO KITTY	Assign Date		23/08/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA TIGER GL200R	c.c		197	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	MH1MC2213BK078901	Colour		YELLOW	
	Odometer	75398 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	80/90-18	DUNLOP		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80/90-18	CHEETAH		5 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
5. General Information						
	Accident Date	03/08/2021	Inspect Date /	Time	24/08/2021 ( 05:30 PM )	
	Survey held at	M 1 MOTORING				
	411 CHANGI ROAD SINGAPORE 419860					
_	Remarks					
5a.		A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000				
5a.	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL	STIMATE WAS NOT PRESENTE /AS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE	D AT THE TIME O STIMATE. E PHOTOGRAPHS	F INSPE	CTION.	
5a.	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL	STIMATE WAS NOT PRESENTE AS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE D REPAIR COST OF THE DAMA	D AT THE TIME O STIMATE. E PHOTOGRAPHS	F INSPE	CTION.	

Report Ref No. CS3/ASM21008830/Gvce2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.