

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008831/APA3Q2**Date:** 25/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100471755
Claimant Vehicle No :	SLN6025Z	Insured Vehicle No :	ET6677T
Date of Loss:	20/08/2021	Nature of Claim:	TP
		Claim No:	4484276225SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN6025Z		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5927761
Reg. Date:	09/05/2017 (Man. Year: 2016)	Chassis No:	RU31227749
Colour:	White	Odometer:	155364 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,921.60	4,640.24	5,281.36	53.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,300.00	1,130.00	32.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,351.60	6,940.24	6,411.36	48.02
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	13,351.60	5,500.00	7,851.60	58.81
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		5,860.00		
Global Sum Settlement (S\$)		5,860.00		

INSPECTION

Date of Assignment:	21/08/2021	
Date Inspected:	21/08/2021	Inspected At: ADVANCE AUTO GARAGE (#03-01) (HQ) 10 Kaki Bukit Road 2 #03-01, First East Centre, Singapore 417868
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Deformed	762.70 F	*762.70 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Necessary	47.00 F	*47.00 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	282.20 F	*- FL
7	1		*REAR BUMPER UNDER COVER	Not Necessary	225.10 F	*- FL
8	1		*REAR BUMPER UNDER COVER CLIPS	Not Necessary	30.00 FS	*- FS
9	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
10	1		*REAR END PANEL	Dented	585.00 F	*585.00 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	136.50 F	*136.50 FL
12	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	10.00 FS	*10.00 FS
13	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
14	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	85.20 F	*- FL
15	1		*REAR END PANEL BUZZER SENSOR	Damaged	90.80 F	*90.80 FL
16	1		*TAILGATE	Distorted	1,100.00 F	*1,100.00 FL
17	1		*TAILGATE LOCK	Damaged	182.50 F	*182.50 FL
18	1		*TAILGATE WEATHERSTRIPE	Cut	165.40 F	*165.40 FL
19	1		*TAILGATE INNER TRIM BOARD	Cracked	285.60 F	*285.60 FL
20	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
21	1		*TAILGATE OUTER GARNISH	Not Necessary	325.00 F	*- FL
22	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
23	1		*TAILGATE REFLECTOR	N/S Cracked	826.40 F	*413.20 FL
24	1		*TAILGATE GLASS MOULDING	Necessary	120.00 F	*120.00 FL
25	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
26	2		*TAILGATE DAMPER	Not Necessary	365.40 F	*- FL
27	1		*HONDA LOGO	Not Necessary	30.40 F	*- FL
28	1		*VEZEL WORDING	Necessary	45.90 F	*45.90 FL
29	1		*HYBRID EMBLEM	Necessary	58.90 F	*58.90 FL
30	2		*TAILLAMP	Not Necessary	949.20 F	*- FL
31	1		*TAILLAMP LOWER APRON	N/S Deformed	390.00 F	*195.00 FL
32	1		*REAR FENDER INNER TRIM BOARD	N/S Cracked	710.40 F	*305.20 FL
33	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
34	1		*SPARE TYRE PANEL TOP BOARD	Deformed	306.60 F	*306.60 FL
35	1		*REAR EXHAUST PIPE	Not Necessary	598.60 F	*- FL
36	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	28.50 F	*- FL
37	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	98.30 F	*- FL
38	1		*REAR CAMERA	Damaged	480.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,921.60	5,600.30
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	960.06
Total Parts (\$)	9,921.60	4,640.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	900.00
2	SPRAY PAINTING	New	1,100.00	900.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE REAR VIDEO RECORDER	New	100.00	50.00
8	TO REMOVE UPHOLSTERY	New	150.00	60.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
11	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			3,430.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >