

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121008834/UTF3N2**Date:** 27/09/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : GBG8323E **Insured Vehicle No :** WC2557J

Date of Loss: 20/08/2021 Nature of Claim: TP Claim No: CDMCG21001567

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG8323E**

Make & Model: TOYOTA HIACE, 3.0 D DX (A) Engine No: 1KD2751254

Reg. Date: 15/11/2017 (Man. Year: 2017) Chassis No: KDH2015029634

Colour: White/Maroon Odometer: 167435 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 195R15

Front Left Side: Austone 6 mm Rear Left Side: Austone 6 mm

Front Right Side: Austone 6 mm Rear Right Side: Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,175.30	8,404.24	6,771.06	44.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	3,500.00	630.00	15.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,305.30	11,904.24	7,401.06	38.34
Approved Total (Overridden) (S\$)		9,500.00		
Nett Amount (S\$)	19,305.30	9,500.00	9,805.30	50.79

INSPECTION

Date of Assignment: 23/08/2021

Date Inspected: 23/08/2021 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @
KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2021)
Parts:	213	TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG8323E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE	Badly Dented	2,135.20 F	*2,135.20 FL
2	1	*REAR TAILGATE INNER LOCK	Dented/Jammed	359.00 F	*359.00 FL
3	1	*REAR TAILGATE INNER TRIM BOARD	Deformed/Torn	248.30 F	*248.30 FL
4	1	*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
5	1	*REAR TAILGATE OUTER HANDLE GARNISH	Not Necessary	366.50 F	*- FL
6	1	*REAR TAILGATE TOYOTA MOTIF	Necessary	68.50 F	*68.50 FL
7	1	*REAR TAILGATE DAMPER O/S	Twisted/Bent	322.10 F	*322.10 FL
8	1	*REAR TAILGATE WEATHERSTRIP	Twisted	426.70 F	*386.21 FL
9	1	*REAR TAILGATE WINDSCREEN GLASS	Shattered	1,311.30 F	*1,311.30 FL
10	1	*REAR TAILGATE WINDSCREEN GLASS MOULDING	No such part	219.00 F	*- FL
11	1	*REAR BUMPER	Distorted	841.60 F	*566.01 FL
12	1	*SET REAR BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
13	1	*REAR BUMPER SIDE HOLDER O/S	Cracked	139.00 F	*105.00 FL
14	1	*REAR BUMPER INNER STEP PANEL	Bent	380.40 F	*199.20 FL
15	1	*REAR END PANEL INNER	Badly Dented	936.20 F	*645.10 FL
16	1	*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
17	1	*REAR END PANEL TOP PLATE	Not Necessary	299.50 F	*- FL
18	1	*REAR TAILLAMP	O/s Broken	732.60 F	*366.30 FL
19	1	*REAR TAILLAMP LOWER GARNISH O/S	Torn	435.20 F	*150.20 FL
20	1	*REAR TAILLAMP HOUSING PANEL OUTER O/S	Badly Dented	325.30 F	*325.30 FL
21	1	*REAR TAILLAMP INNER FILTER PANEL O/S	Badly Dented	366.80 F	*366.80 FL
22	1	*REAR FENDER (BODY PANEL)	Badly Dented/Buckled	1,645.20 F	*1,645.20 FL
23	1	*REAR FENDER INNER PANEL	Repair	1,069.10 F	*- FL
24	1	*REAR FENDER INNER TRIM BOARD	Torn	288.50 F	*288.50 FL
25	1	*REAR FENDER OUTER RAILING	Not Necessary	315.20 F	*- FL
26	1	*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
27	1	*REAR TAILGATE 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
28	1	*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
29	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
30	1	*REAR BUMPER REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
31	1	*REAR FLOOR PANEL TOP WOODEN BOARD	Cracked	680.00 FS	*480.00 FS
32	1	*SET REAR CORPORATE ADVERTISEMENT & ARTWORK	Necessary	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,175.30	10,942.32
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,538.08
Total Parts (\$\$)	15,175.30	8,404.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	100.00	60.00
3	REMOVE & INSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	100.00
4	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	80.00	40.00
5	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	2,200.00	2,000.00
6	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	1,500.00	1,200.00
7	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	80.00
Gross Labour Cost (\$\$)			4,130.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >