

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008837/UUCN2**Date:** 24/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00106212001

Claimant Vehicle No : SMS7815R **Insured Vehicle No :** SKP6560X

Date of Loss: 20/08/2021 Nature of Claim: TP Claim No: SNM21D204663/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS7815R**

Make & Model: RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A) Engine No: K9KF649D016055

Reg. Date: 28/11/2017 (Man. Year: 2017) Chassis No: VF1RFA00858580911

Colour: Grey Odometer: 91908 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R20 Rear Tyre Size: 195/55R20

Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,553.64	4,965.84	11,587.80	70.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	1,360.00	2,440.00	64.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,353.64	6,325.84	14,027.80	68.92
Approved Total (Overridden) (\$\$)		5,050.00		
Nett Amount (\$\$)	20,353.64	5,050.00	15,303.64	75.19

INSPECTION

Date of Assignment: 23/08/2021

Date Inspected: 24/08/2021 Inspected At: Blk 15 Kaki Bukit Road 4,
Bartley Biz Centre,
#01-53
Zoom Autowerks Pte Ltd

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Sep 2021)

Parts: M1-MPV RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS7815R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOP	Dented/Deformed	1,386.40 FL	*1,386.40 FL
2	1		*REAR BUMPER TOP GARNISH	Deformed	48.60 FL	*48.60 FL
3	1		*REAR BUMPER CENTRE (BLACK)	Cut/Deformed	698.70 FL	*698.70 FL
4	1		*REAR BUMPER LOWER	Deformed	486.70 FL	*486.70 FL
5	1		*REAR BUMPER CENTRE LOWER	No such part	425.80 FL	*- FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	397.20 FL	*- FL
7	2		*REAR BUMPER SIDE RETAINER	Not Necessary	98.80 FL	*- FL
8	1		*REAR BUMPER CENTRE BRACKET	Cracked	320.50 FL	*320.50 FL
9	2		*REAR BUMPER BRACKET	Not Necessary	304.60 FL	*- FL
10	1		*REAR ULTRASOUND SENSOR (4 Pcs)	Shorted (2 Pcs only)	1,187.20 FL	*360.00 FL
11	1		*REAR ULTRASOUND SENSOR O-RING SET	Not Necessary	76.50 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	660.80 FL	*660.80 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	295.60 FL	*- FL
15	1		*REAR END PANEL	Repair	786.50 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
17	1		*REAR TAILGATE	Repair	1,671.20 FL	*- FL
18	1		*REAR TAILGATE GLASS SEALER	Not Necessary	359.50 FL	*- FL
19	1		*REAR TAILGATE INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
20	1		*REAR TAILGATE INNER LOCK	Not Necessary	245.90 FL	*- FL
21	1		*REAR TAILGATE GARNISH	Warped	1,163.40 FL	*1,163.40 FL
22	1		*REAR TAILGATE GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
23	1		*REAR TAILGATE EMBLEM (RENAULT)	Necessary	72.40 FL	*72.40 FL
24	1		*REAR TAILGATE EMBLEM (SCENIC)	Necessary	117.50 FL	*117.50 FL
25	1		*REAR TAILGATE LOGO	Necessary	142.60 FL	*142.60 FL
26	2		*REAR TAILGATE DAMPER	Not Necessary	390.40 FL	*- FL
27	1		*REAR TAILGATE WEATHER STRIP	Not Necessary	268.50 FL	*- FL
28	2		*REAR TAILLAMPS	Not Necessary	1,450.80 FL	*- FL
29	1		*REAR TAILLAMPS CLIPS	Not Necessary	32.00 FL	*- FL
30	2		*REAR FENDER INNER TRIMBOARD	Not Necessary	1,540.80 FL	*- FL
31	1		*REAR FENDER INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
32	1		*REAR FLOOR PANEL TOP TRAY	Not Necessary	245.70 FL	*- FL
33	1		*REAR FLOOR PANEL	Not Necessary	1,451.60 FL	*- FL
34	1		*REAR EXHAUST CHROME MUFFLER	Not Necessary	120.00 FL	*- FL
35	1		*REAR EXHAUST END PIPE	Not Necessary	785.00 FL	*- FL
36	2		*REAR EXHAUST MOUNTING	Not Necessary	108.40 FL	*- FL
37	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
39	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*REAR TAILGATE GLASS SEALANT	Not Necessary	80.00 FS	*- FS
41	1		*REAR EXHAUST GUM	Not Necessary	120.00 FS	*- FS
42	1		*REAR NUMBER PLATE W/GARNISH	Serviceable	68.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,317.60	5,517.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,763.96	551.76

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	16,553.64
						4,965.84
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	550.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	600.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH	New	150.00	60.00
5	TO REMOVE & INSTALL REAR FLOOR COMPONENTS,TRIM & GARNISH	New	150.00	80.00
6	TO REMOVE & INSTALL REAR TAILGATE GLASS	New	150.00	0.00
7	TO RE-POSITION,DRILL & INSTALL REVERSE SENSOR	New	150.00	50.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	0.00
Gross Labour Cost (\$\$)			3,800.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >