

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21008842/EEA3Q2**Date:** 15/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900117683
Claimant Vehicle No :	SFR1088A	Insured Vehicle No :	SMN3751T
Date of Loss:	19/08/2021	Nature of Claim:	TP
		Claim No:	6715434967SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFR1088A	Engine No:	CHZC31630
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Chassis No:	WAUZZZGA5KA073794
Reg. Date:	24/08/2019 (Man. Year: 2019)	Odometer:	17361 km
Colour:	Red		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,903.00	1,523.20	1,379.80	47.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,972.00	2,272.00	1,700.00	42.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,875.00	3,795.20	3,079.80	44.80
+ GST 7.00/7.00% (S\$)	481.25	265.66	215.59	44.80
Nett Amount (S\$)	7,356.25	4,060.86	3,295.39	44.80
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,312.86		

INSPECTION

Date of Assignment:	23/08/2021		
Date Inspected:	17/09/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,280.00 FS	*1,024.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	77.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	284.00 FS	*227.20 FS
4	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	43.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR LH/RH	Not Necessary	60.00 FS	*- FS
6	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	579.00 FS	*- FS
7	2		*REAR BUMPER HOLDING STRAP	Not Necessary	26.00 FS	*- FS
8	2		*REAR BUMPER SENSOR INNER (NPA)	Not Necessary	0.00 FS	*- FS
9	4		*REAR SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
10	2		*REAR WHEEL COVER LH/RH	Necessary	340.00 FS	*272.00 FS
11	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
					Total Parts (\$)	2,903.00 1,523.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR AND RESPRAY REAR END PANELLING	New	500.00	250.00
2	TO RESPRAY REAR END PANELLING	New	800.00	500.00
3	TO REMOVE AND REINSTALL REAR PARKING AID CHECK FUNCTION	New	280.00	280.00
4	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
5	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,972.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >