



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 9598Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR RH	DENTED	1,210.00	1,210.00
1	REAR DOOR PROTECTOR FILM RH	NECESSARY	45.00	45.00
1	REAR DOOR LOWER GARNISH RH	MISSING	145.00	145.00
1	REAR FENDER LOWER GARNISH RH	CUT	95.00	95.00
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER (NPA)	NOT NECESSARY	-	-
1	REAR RIM 17 INCH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR LOWER ARM RH (ADDITIONAL)	BENT	335.00	335.00
1	REAR KNUCKLE ARM RH (ADDITIONAL)	BENT	485.00	360.00
1	REAR WHEEL HUB WITH BEARING RH (ADDITIONAL)	JAMMED	345.00	250.00
	LESS 20% DISCOUNT		-532.00	-488.00
			2,128.00	1,952.00
	<u>SPECIAL NETT ITEMS</u>			
1	SIDE SKIRT STEP UP RAILS ASSY RH (SN)	CUT	680.00	500.00
1	REAR TYRE RH 225/60R17 (SN) (\$250.00) (80%)	TORN	280.00	200.00
			960.00	700.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND REAR RIM 17 INCH.		800.00	500.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		800.00	400.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		60.00	30.00
	CHECK AND WHEEL COMPUTERIZE ALIGNMENT.		80.00	60.00
	TO REMOVE AND REFIX FRONT TYRE AND WHEEL BALANCING IN ORDER TO REAR RIM LH.		50.00	30.00

Report Ref No. CS/SMR21008848/Euf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE REAR UNDERCARRIAGE RH. (ADDITIONAL)		200.00	150.00
			1,990.00	1,170.00
GRAND TOTAL			5,078.00	3,822.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CS/SMR21008848/Euf3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.