

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 5871X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
1	BACK SENSOR 1G3 GREY ME (SN)	NOT NECESSARY	101.05	-
1	REFLECTOR ASSY (SN)	NOT NECESSARY	60.40	-
1	REFLECTOR ASSY (SN)	NOT NECESSARY	60.40	-
1	ANTENNA, ELECTRICAL (SN)	NOT NECESSARY	194.20	-
1	COVER, RR BUMPER (SN)	DENTED	561.50	561.50
12	PIECE, RR BUMPER (SN)	NECESSARY	54.00	49.20
1	RETAINER, RR BUMPER (SN)	BROKEN	59.70	59.70
1	RETAINER, RR BUMPER (SN)	BROKEN	59.70	59.70
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	144.00	-
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	144.00	-
1	REINFORCEMENT (SN)	NOT NECESSARY	219.20	-
1	SPOILER, RR NO.1 (SN)	CUT	856.90	856.90
12	RETAINER, OUTSIDE (SN)	NOT NECESSARY	48.00	-
1	COVER SUB-ASSY, RR (SN)	NOT NECESSARY	553.00	-
			3,166.05	1,617.00
	<u>LABOUR</u>			
	TO RESET ECU AND REPROGRAMME.	NOT NECESSARY	180.00	-
	TO CHECK WIRING AND LIGHTING. TO WATER TEST FO LEAK.		122.40	122.40
	R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.		180.00	180.00
	TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN / REALIGN ALL OTHER AFFECTED AREAS.		2,160.00	720.00
	TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.		1,770.00	590.00
			4,412.40	1,612.40
	GRAND TOTAL		7,578.45	3,229.40

Report Ref No. CS/SMR21008857/Euf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 3,229.40

Report Ref No. CS/SMR21008857/Euf3e2



Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator